

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD State of New Mexico
Energy Minerals and Natural Resources
Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

JAN 07 2015

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Zia Water LLLP c/o Atkins Engineering Associates, Inc.	Contact: Christopher Cortez (Atkins Engineering Associates, Inc.)
Address: 2904 W 2nd St, Roswell, NM 88201	Telephone No.: 575.624.2420
Facility Name: Marathon Road Water Station (MRWS)	Facility Type: Fresh Water Station
Surface Owner: BLM	Mineral Owner: unknown
API No. n/a	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	25	19S	34E	170	South	2237	West	Lea

Latitude 32°37'28.46"N Longitude 103°30'54.33"W

NATURE OF RELEASE

Type of Release: Apparent Produced Water	Volume of Release: unknown	Volume Recovered: 110 bbl
Source of Release: Unknown Truck Dump	Date and Hour of Occurrence: unk.	Date and Hour of Discovery: 1/6/15 7-8am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Thomas Oberding NMOCD Hobbs Office, lvm with BLM Carlsbad	
By Whom? Christopher Cortez	Date and Hour: 1/06/2015 at 10:03 am.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* n/a

Describe Cause of Problem and Remedial Action Taken.*
Unauthorized dumping of apparent produced water behind fresh water filling ports at Marathon Road Water Station (MRWS). Lea County Sheriff contacted who forwarded to NM State Police. Voicemail left at BLM-Carlsbad office. Dumping believed to occur during the night of 1/05/2015 -1/06/2015. Vacuum extraction of standing fluid completed at approximately 12:40pm 1/06/2015

Describe Area Affected and Cleanup Action Taken.*
Approximately 19,000 sq feet located on the south side of the Marathon Road Water Station. Vacuum Extraction and disposal of standing fluids. Fluid and top 1-2" soil samples sent to Hall Environmental Analysis Laboratory for characterization (BTEX, TPH, RCRA Metals, Chlorides-Aqueous; BTEX, TPH-soil). Contractor and disposal options being explored. Soil to be excavated with field screening of VOCs using Photo-ionization detector, regraded and restored to pre-dump condition. Possible fresh water leak in the vicinity of dump on station may result in more standing water on site in spill area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Christopher Cortez	Approved by Environmental Specialist:	
Title: Operations Manager	Approval Date: 1-7-15	Expiration Date: 3-7-15
E-mail Address: chris@atkinseng.com	Conditions of Approval: <i>Site Specific Response, Delivered and complete area as per NMOCD guidelines. Submit final C-141 by 3-7-15.</i>	
Date: 1/06/2015 Phone: 575.624.2420	Attached <input type="checkbox"/> IRP-3980 300831	

* Attach Additional Sheets If Necessary

FTO 1500727722
N701500728058
P701500728392

JAN 08 2015