

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

FAB1436456327

Release Notification and Corrective Action

NAB1501242877

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Enterprise Field Services LLC	Contact Dina Babinski
Address PO Box 4324, Houston TX 77252	Telephone No. 210-528-3824
Facility Name Pipeline ROW, Trunk A Gathering Lateral	Facility Type Gas Gathering Pipeline

Surface Owner Private Owner	Mineral Owner NA - Pipeline	API No. NA
------------------------------------	------------------------------------	-------------------

LOCATION OF RELEASE

Unit Letter N	Section 21	Township 23S	Range 31E	Feet from the 219	North/South Line NORTH	Feet from the 659	East/West Line EAST	County Eddy
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	-----------------------------	-------------------------------	-----------------------

Latitude N 32.285710 Longitude W -103.784860

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 107 MCF	Volume Recovered NA
Source of Release Pipeline Blowdown, Overpressure	Date and Hour of Occurrence 12/30/2014 @ 15:25 MST	Date and Hour of Discovery 12/30/2014 @ 16:00 MST
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NM OIL CONSERVATION	

ARTESIA DISTRICT
JAN 09 2015

RECEIVED



Describe Cause of Problem and Remedial Action Taken.*

Due to low temperatures, hydrates formed on the pipeline, and a pipeline blowdown occurred during defrosting. Pipeline liquids were collected and temporarily stored in frac tanks until removed from the location via tanker trucks. No liquid was released to the ground.

Describe Area Affected and Cleanup Action Taken.*

No liquid spills occurred requiring any cleanup actions.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Jon E. Fields	Approved by	Signed By 	
Title: Director, Field Environmental	Approval Date: 1/12/14	Expiration Date: N/A	
E-mail Address: jefields@eprod.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>	
Date: 1-5-2015	Phone: 713-381-6684		

* Attach Additional Sheets If Necessary

2RP-2723



Enterprise
Products

ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

NM OIL CONSERVATION

ARTESIA DISTRICT

JAN 09 2015

RECEIVED

7014 2120 0001 5336 8643
Return Receipt Requested

January 5, 2015

Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report for Enterprise Field Services LLC
Releases on Carlsbad Area Gathering Lines**

Dear Mr. Bratcher:

Enclosed, please find the required C-141 Form for the unplanned blowdown on our Trunk A Line in Eddy County on December 30, 2014. The pipeline was blown down during response to a line freeze. This report is sent pursuant to NMAC 19.15.29 requirements for minor releases.

If you have any questions or need additional information, please contact Dina Babinski, our area Environmental Supervisor by phone at 210-528-3824 or via email at djbabinski@eprod.com or me at 713-318-6684.

Regards,

Jon E. Fields
Director, Field Environmental

/bjm
Attachment