

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JAN 13 2015
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RELEASE
Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Livingston Ridge 19 Federal #1CTB	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-025-35960

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	19	22S	32E					Lea County, NM

Latitude N 32.382350° Longitude W 103.72136°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	10 bbls	Volume Recovered	0 bbls
Source of Release	External corrosion on a 2" steel production flow line	Date and Hour of Occurrence	06/23/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Tomas Oberding, Geoffrey Leking-NMOCD; Jennifer Van Curen- BLM		
By Whom?	Kathy Purvis	Date and Hour	06/23/2014 @ 2:20 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

External corrosion on a 2" steel production flow line caused 10 bbls of oil to leak onto the ground. No fluids were recovered and the line was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 10' x 10' on and off location. Remediation was completed in accordance with the remediation plan approved by Tomas Oberding of NMOCD via email on 10/15/2014 and approved by Sol Hughes of the BLM via email on 10/15/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge, and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				OIL CONSERVATION DIVISION	
Printed Name:	Chancey Summers			Approved by Environmental Specialist:	
Title:	HES Specialist			Approval Date:	1-12-15
E-mail Address:	Chancey.Summers@oxy.com			Expiration Date:	
Date:	1-7-15			Conditions of Approval:	
Phone:	(575) 397-8216			Attached	<input type="checkbox"/>
				IRP-3172	

* Attach Additional Sheets If Necessary

JAN 13 2015

p 70 1419554819