

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBSOCD

State of New Mexico
JAN 13 2015
Energy Minerals and Natural Resources
Oil Conservation Division
220 South St. Francis Dr.
Santa Fe, NM 87505
RECEIVED

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company- Harvey E. Yates Company	Contact- Tammy R. Link
Address - P.O. Box 1933, Roswell, NM 88201-1933	Telephone No. 575-623-6601
Facility Name - Richardson Unit #1	Facility Type - API #30-025-27783

Surface Owner - Fee	Mineral Owner	API No. 30-025-27783
---------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter M	Section 32	Township 13S	Range 36E	Feet from the 660'	North/South Line S	Feet from the 660'	East/West Line W	County Lea
------------------	---------------	-----------------	--------------	-----------------------	-----------------------	-----------------------	---------------------	---------------

Latitude 32.142712 N Longitude 103.332926 W

NATURE OF RELEASE

Type of Release - (ILLEGAL DUMPING) of Produced Water	Volume of Release - 100 bbls	Volume Recovered - 0-
Source of Release	Date and Hour of Occurrence 12/17/14 after 5:00 pm	Date and Hour of Discovery-12/18/14 5:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Bill with OCD in Hobbs	
By Whom?	Date and Hour 12/19/14 at 11:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Illegal dumping of produced water.

Describe Area Affected and Cleanup Action Taken.*

Backhoe scraped top layer and haul off contaminated soil, pulled samples. See attachment for location layout and soil sample results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Tammy R. Link		Approved by Environmental Specialist:	
Title: Engineering Tech		Approval Date: 1-12-15	Expiration Date: —
E-mail Address: tlink@heycoenergy.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/12/2015	Phone: 575-623-6601	—	10P-3470

* Attach Additional Sheets If Necessary

JAN 13 2015