

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

~~HOBBS OGD~~ State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505
RECEIVED

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Jay Garcia	
Address: 29 Vacuum Complex Lane	Telephone No. 575-704-2455	
Facility Name: Santa Fe #133	Facility Type: Tank Batterys	
Surface Owner: NMOCD	Mineral Owner: NMOCD	API No. 30-025-32333

LOCATION OF RELEASE

Unit Letter O	Section 31	Township 17S	Range 35E	Feet from the 435	North/South Line South	Feet from the 1930	East/West Line East	County LEA
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	----------------------

Latitude **32.7854367361682** Longitude **103.494735819723**

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 6.27 BBLS	Volume Recovered: 0 BBLS
Source of Release: Tank overflow	Date and Hour of Occurrence 01/04/2015 10:30 am	Date and Hour of Discovery 01/04/2015 4:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding	
By Whom? Jay Garcia	Date and Hour: 01/07/2015 10:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

ENV – Agency Reportable – 3 BO & 17 BPW – Santa Fe #133– RR II – MCBU – Buckeye:
On Sunday January 4th, 2015 @ 10:30 Hrs. MST, at Santa Fe #133, a water tank overflow was found during normal rounds resulting in a release of 3 bbls of oil and 17 bbls of produced water. 2 bbl. of oil and 13 bbl. of produced water were recovered. The affected area will be remediated according to NMOCD and COPC and BLM guidelines. This is not a PSE. Consequence: 1, Likelihood: 5, RR: II

Describe Area Affected and Cleanup Action Taken.*

Release of 17 barrels produced water and 3 barrels of oil. Recovered 13 barrels of produce water and 2 barrels of oil. Affected area was 110 foot by 60 foot X 2 inch deep o caliche pad and was not contained. The affected area will be remediated according to NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jay Garcia</i>		OIL CONSERVATION DIVISION	
Printed Name: Jay Garcia		Approved by Environmental Specialist:	
Title: LEAD HSE	Approval Date: <i>1-9-15</i>	Expiration Date: <i>3-9-15</i>	
E-mail Address: jay.c.garcia@conocophillips.com	Conditions of Approval: <i>See Signer report Release & remediate area upon NMOCD guide. Submit final C-141 by 2-9-15</i>		Attached <input type="checkbox"/>
Date: 01/07/2015	Phone: 575-704-2455	<i>IRP 3494</i>	

JAN 13 2015

217817
N70 15009 35 732
P70 15009 36051