

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Fasken Oil and Ranch, Ltd	Contact: Aaron Pachlhofer
Address: 6101 Holiday Hill Road, Midland, TX, 79707	Telephone No.: 432-687-1777
Facility Name: Ling Federal #2	Facility Type: Gas well

Surface Owner: BLM	Mineral Owner: BLM	API No.: 30-025-30336
--------------------	--------------------	-----------------------

LOCATION OF RELEASE

Unit Letter NWSW	Section 31	Township 19S	Range 34E	Feet from the	North/South Line	Feet from the	East/West Line	County LEA
---------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Condensate	Volume of Release 186	Volume Recovered 5
Source of Release: Piping	Date and Hour of Occurrence: N/A	Date and Hour of Discovery 1/5/15, 11:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Reported	
By Whom? Aaron Pachlhofer	Date and Hour: 1/6/15, 10:00 a.m. to Tomas Oberding/Jeff Robertson	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



Pipe between oil tank and water take burst due to inclement weather. Broken pipe has been fixed

Describe Area Affected and Cleanup Action Taken.*

Affected area calculated at approximately 3,100 square feet. Pooled liquids have been recovered. Further remedial action is pending discussion with BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Aaron Pachlhofer, P.G.	Approval Date: 1-9-15	Expiration Date: 3-9-15
Title: Environmental Coordinator	Conditions of Approval: <i>Site system repaired. Patched & covered in area as per NMOCD guidelines. Submit final C-141 by 3-9-15.</i>	
E-mail Address: aaronp@forl.com	Attached <input type="checkbox"/> IRP-3495	
Date: 1/7/15 Phone: 432-687-1777	151416	

* Attach Additional Sheets If Necessary

7015009 37000
7015009 37178

JAN 13 2015