

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: Chevron USA Inc.	Contact: Edem Sededji	
Address: 15 Smith Rd., Midland, TX, 79705	Telephone No. 432-234-4437	
Facility Name: New Mexico 'O' State NTC- 1 036	Facility Type: Oil Well	
Surface Owner: N/A	Mineral Owner	API No. 30-025-32339

LOCATION OF RELEASE

Unit Letter N	Section 36	Township 17S	Range 34E	Feet from the 330	North/South Line South	Feet from the 2210	East/West Line West	County LEA
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.7851 Longitude -103.5155

NATURE OF RELEASE

Type of Release: Release to Land	Volume of Release: 600 bbls of Produced Water	Volume Recovered: 600 bbls
Source of Release: Well Head	Date and Hour of Occurrence: 11/17/2014 08:00 AM	Date and Hour of Discovery 11/17/2014 08:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Dr. Tomas Oberding	
By Whom? Edem Sededji	Date and Hour: 12/17/2014 03:30 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Spill was due to frozen valve at the wellhead.		
Describe Area Affected and Cleanup Action Taken.* The area affected was around the wellhead location. A vacuum truck recovered 600 bbls of fluid and contaminated dirt was removed.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		


HOBBS OGD

JAN 03 2015

RECEIVED

JAN 13 2015

OIL CONSERVATION DIVISION

 Invalid signature

X Edem Sededji

Edem Sededji
HE Specialist

Signature: Signed by: Edem Sededji

Printed Name: Edem Sededji

Title: HE Specialist

E-mail Address: etpo@chevron.com

Date: 01/09/2015

Phone: 432-234-4437

Approved by Environmental Specialist:

Approval Date: 1-9-15

Expiration Date: —

Conditions of Approval:

Attached ☐

RP-3498

* Attach Additional Sheets If Necessary

4323
N-101500939888
P-101500940036
HUBBS/OCD
JAN 09 2015
RECEIVED