

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBS OCD**

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

JAN 12 2015

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Lusk Deep Unit a #22H	Facility Type: Well

Surface Owner: Federal	Mineral Owner:	API No. 30-025-40705
------------------------	----------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	17	19S	32E	380	North	1770	West	Lea

Latitude 32.6668204887527 Longitude -103.791219305425

**NATURE OF RELEASE**


Type of Release: Produced Water	Volume of Release: 150 bbls	Volume Recovered: 70 bbls
Source of Release: Flowline	Date and Hour of Occurrence: 12/12/2014 8:00 pm	Date and Hour of Discovery: 12/12/2014 8:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding - NMOCD / Jeff Robertson - BLM	
By Whom? Lupe Carrasco	Date and Hour: 12-13-2014	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
This release was caused by a third party contractor, Sweatt Construction, using a dozer. The driver punctured the poly line while moving it. Vacuum trucks were dispatched and all standing fluid was disposed of at NMOCD approved facility.

Describe Area Affected and Cleanup Action Taken.\*  
The impacted area is located in a pasture adjacent to the location. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 1-12-15	Expiration Date: 3-12-15
E-mail Address: atrujillo@concho.com	Conditions of Approval: <i>Sites updated &amp; report. Admin</i>	Attached <input type="checkbox"/> IRP-3498
Date: January 9, 2015 Phone: 575-748-6940		

\* Attach Additional Sheets If Necessary

JAN 13 2015

229137  
N701501231968  
P701501232141