

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION** Form C-141  
ARTESIA DISTRICT Revised October 10, 2003

JAN 15 2015  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

RECEIVED

**Release Notification and Corrective Action**

NAB1502037424

**OPERATOR**

Initial Report  Final Report

Name of Company: <b>Oxy Permian LTD (192463)</b>	Contact: <b>Chris Jones</b>
Address: <b>1502 W. Commerce, Carlsbad, NM 88220</b>	Telephone No.: <b>575-628-4121</b>
Facility Name: <b>North Burton Flats Battery (Government AA #2)</b>	Facility Type: <b>Central Tank Battery</b>

Surface Owner: <b>Federal</b>	Mineral Owner	API#: <b>30-015-33283</b> Lease No.: <b>NM 18293</b>
-------------------------------	---------------	---

**LOCATION OF RELEASE**

Unit Letter <b>D</b>	Section <b>23</b>	Township <b>20S</b>	Range <b>28E</b>	Feet from the	North/South Line	Feet from the	East/West Line	County: <b>Eddy, NM</b>
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	-------------------------

Latitude 32.5658815 N Longitude -104.1557648 W

**NATURE OF RELEASE**

Type of Release: <b>Oil</b>	Volume of Release: <b>15 bbls</b>	Volume Recovered: <b>10 bbls</b>
Source of Release: <b>Gas Supply Line</b>	Date and Hour of Occurrence: <b>1/5/2015</b>	Date and Hour of Discovery: <b>1/6/2015 11:19 am</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>OCD/Mike Bratcher via telephone</b> <b>BLM/Jim Amos via email</b>	
By Whom: <b>Kimberly M. Wilson</b>	Date and Hour: <b>1/8/2015 10:00 am</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A gas supply line froze and lost pressure sending the fluid to the field vent releasing 15 barrels of oil. The facility was shut-in and the gas line repaired. A vac truck was immediately called to the location and recovered 10 barrels of oil.

Describe Area Affected and Cleanup Action Taken.\* The area impacted measured approximately 20'x12' inside the containment. The oil breached the berms and impacted approximately 25'x15 onto the location. Talon/L.P.E has been contracted to complete site assessment and remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		<b>OIL CONSERVATION DIVISION</b>	
Signature: <b>Chris Jones</b>	Approved by District Supervisor: 		
Printed Name: <b>Chris Jones</b>	Approval Date: <b>1/16/15</b>	Expiration Date: <b>NA</b>	
Title: <b>HES Specialist</b>	Conditions of Approval:		
E-mail Address: <b>Christopher_Jones@oxy.com</b>			Attached <input type="checkbox"/>
Date: <b>1/9/2015</b> Phone: <b>575-628-4121</b>	<p><b>Remediation per O.C.D. Rules &amp; Guidelines</b>  <b>SUBMIT REMEDIATION PROPOSAL NO</b>  <b>LATER THAN: <u>2/16/15</u></b></p>		

\* Attach Additional Sheets If Necessary

2RP-2745

## **Patterson, Heather, EMNRD**

---

**From:** Kimberly M. Wilson <kwilson@talonlpe.com>  
**Sent:** Thursday, January 15, 2015 1:28 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Jim Amos (jamos@blm.gov)  
**Cc:** Christopher\_Jones@oxy.com; David Adkins  
**Subject:** North Burton Flats \* 30-015-33283 \* Lease # NM-18293 \* DOR 1-5-2015  
**Attachments:** N Burton Flats Battery initial C-141 DOR 1-5-15.pdf

Hello everyone,

Please find attached the initial C-141 for the above referenced release. The facility is closest to the Government AA #2.

Respectfully submitted,

***Kimberly M. Wilson***

Project Manager  
Talon/LPE  
408 West Texas Avenue  
Artesia, New Mexico 88210  
Office: 575.746.8768  
Fax: 575.746.8905  
Cell: 575.602.3826  
Emergency: 866.742.0742  
Email: [kwilson@talonlpe.com](mailto:kwilson@talonlpe.com)  
Web: [www.talonlpe.com](http://www.talonlpe.com)



Better Business Bureau Torch Award for Marketplace Ethics: 2010 Winner, 2009 Finalist  
Staples Foundation for Learning Hall of Fame Recipient: 2010  
ICIC and Business Week- Top 100: 2010, 2009, 2008, 2007, 2006  
Inc. 500/5000: 2012, 2011, 2010, 2009, 2008, 2007

ENVIRONMENTAL RELEASE NOTIFICATION

Call-In Sheet

Date: 1/8/15

Notice received by: MB

Ory USA
Name of Company/Phone #

N. Burton Flents CTB
Facility Name

30-015-33283, 23, 20s - 28e, 1/6/15
API #, Sec., Township Range, Date of Occurrence

Date/Hour of Discovery, Type of Release: O.I., Volume of Release: 15 bbls, Volume Recovered: 10 bbls

Briefly Describe Cause of Problem and action taken: Release due to cold weather - Freeze-ups

K Wilson w/ Talon, 1/8/15 8 AM
Notice given by: Name/ Company, Date/Hour Immediate Notice given

Date C-141 received: 2RP-

\*\*\*\*\*

FLARE NOTIFICATION

Call-In Sheet

Date:

Notice received by:

Name of Company/Phone #

Facility Name

Date of Occurrence, Date/Hour of Flare, Type of Release

Flared MCF Volume, Volume Recovered

Briefly Describe Cause of Problem and action taken:

Notice given by: Name/ Company

Date/Hour Immediate Notice given

Date C-141 received: 2RP-