

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Apache Corporation	Contact	Larry Baker
Address	8 Ellison Lane Eunice, NM	Telephone No.	432-631-6982
Facility Name	E Woods Battery	Facility Type	Battery
Surface Owner	Jay D Martin	Mineral Owner	
		API No.	30-025-39687

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	22	22S	37E	1399'	FNL	1432'	FEL	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	18 Barrels of oil	Volume Recovered	15 Barrels of oil
Source of Release	Heater Treater	Date and Hour of Occurrence	3/3/14	Date and Hour of Discovery	3/3/14
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking		
By Whom?	Larry Baker	Date and Hour	3/4/14		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The gasket on the fire tube failed resulting in the release of oil. The wells were shut in and the gasket was replaced.

Describe Area Affected and Cleanup Action Taken.*

All the standing fluid was contained to the facility, pad, and lease road. An overspray area of oil affected the pasture southwest of the facility. A vacuum truck was dispatched to pick up standing fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Larry Baker</i>		OIL CONSERVATION DIVISION	
Printed Name: Larry Baker		Approved by Environmental Specialist:	
Title: Environmental Technician		Approval Date: 1-15-15	Expiration Date: _____
E-mail Address: larry.baker@apachecorp.com		Conditions of Approval:	
Date: 3-12-14	Phone: 432-631-6982	Attached <input type="checkbox"/> 1AP-3508	

* Attach Additional Sheets If Necessary

873

JAN 27 2015