

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

Form C-141
Revised August 8, 2011

JAN 22 2015
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Apache Corporation	Contact Bruce Baker	
Address 8 Ellison Lane Eunice, NM 88231	Telephone No. (432) 631-6982	
Facility Name Lockhart A -17 Battery (nearest WBDU # 69)	Facility Type Tank Battery	
Surface Owner Chevron	Mineral Owner	API No. 30-025-38204

LOCATION OF RELEASE

Unit Letter I	Section 17	Township 21S	Range 37E	Feet from the 2630'	North/South Line FSL	Feet from the 120'	East/West Line FEL	County Lea
------------------	---------------	-----------------	--------------	------------------------	-------------------------	-----------------------	-----------------------	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release oil and produced water	Volume of Release 20 oil and 480 produced water	Volume Recovered 450 total fluid
Source of Release water transfer line	Date and Hour of Occurrence 2/8/14	Date and Hour of Discovery 2-8-14 at 10:30 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gcoffrey Leking	
By Whom? Bruce Baker	Date and Hour 2/10/14 at 9:00 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The water transfer line froze and ruptured in two separate areas of the line. One area was inside the lined facility containment and the second outside the containment wall. A vacuum truck was dispatched to pick-up standing fluid. The line was repaired.

Describe Area Affected and Cleanup Action Taken.*

The release affected two areas one inside the lined contained facility and the second area was in pasture (4,932 square feet). The standing fluid was picked up and the area was mapped and will be delineated and a corrective action plan will be submitted to NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>		OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Technician		Approval Date: 1-22-15	Expiration Date: 3-22-15
E-mail Address: larry.baker@apachecorp.com		Conditions of Approval: <i>Site Supervisor signed - Delmar & incident was on per NMOCD</i>	Attached <input type="checkbox"/>
Date: 2/20/14	Phone: (432) 631-6982	<i>gunders. submit to C-141 3-22-15</i>	IRP-3509

* Attach Additional Sheets If Necessary

JAN 27 2015

1-10 1902257885
P 70150 2238057