1625 N. French Dr., Hobbs, NM 88240 Energy Minu District II Oil Coll Coll District III Oil Coll 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 Release Notifica Mame of Company COG OPERATING LLC 229/A Address 550 W. Texas, Suite 100, Midland, TX 79701 Facility Name Surface Owner Surface Owner	Contact Pat Ellis Telephone No. 432-230-0077 Facility Type Tank Battery				Submit 2 C			
Unit Letter Section Township Range Feet from the 17 17S 31E	North/	h/South Line Feet from the East/West Line County Eddy				Eddy		
Latitude 32 50.074 Longitude 103 53.446								
NATURE OF RELEASE								
Type of Release Produced water with skim oil Source of Release Water tank			Volume of Release 950bbls Volume			Recovered 750bbls Hour of Discovery		
		09/24/2011			09/24/201	1 7:00 a.m	1.	
Was Immediate Notice Given?	If YES, To Whom? Mike Bratcher-OCD Jim Amos-BLM							
By Whom? Josh Russo			Date and Hour 09/24/2011 5:36 p.m.					
Was a Watercourse Reached?			If YES, Volume Impacting the Watercourse.					
Yes X No If a Watercourse was Impacted, Describe Fully.*								
Describe Cause of Problem and Remedial Action Taken.*								
The water pump locked up and the alarm system failed. The pump has been replaced and the alarm system has been repaired.								
Describe Area Affected and Cleanup Action Taken.*								
Initially 950bbls were released from the water tank due to the faulty water pump and alarm system. We were able to recover 750bbls of fluid. Most of the fluid was contained within the lined tank battery walls. Due to the volume of the release, the water filled up the lined area and some streamed onto a nearby lease road and then into an arroyo. The dimensions measured roughly .3 miles down the lease road and then 425' into the arroyo. The entire spill area has been scraped and contaminated soil was disposed during our emergency response procedures. Tetra Tech will sample the spill site area inside the arroyo to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM prior to any significant remediation work.								
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.								
10-			OIL CONS	ERVA	TION I	DIVISIO	N	
Signature:						A .	-	
Printed Name: Josh Russo	A	Approved by District Supervisor: Signed By Mile Bennetter						
Title: HSE Coordinator	A	JAN 3 1 2013 Approval Date: Expiration Date:						
E-mail Address: jrusso@conchoresources.com		onditions of A				Attached		
Date: 09/30/2011 Phone: 432-212-2399			on per OCD R					
Attach Additional Sheets If Necessary Guidelines. SUBMIT REMEDIATION 7RP-1530								
March = 2013								