

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	BOPCO, LP	Contact	Tony Savoie
Address	522 W. Mermod, Suite 704 Carlsbad, NM 88220	Telephone No.	(432) 556-8730
Facility Name	Poker Lake Unit #79	Facility Type	E & P

Surface Owner	Federal	Mineral Owner:	Federal	Lease No.	B-10679
---------------	---------	----------------	---------	-----------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	2	25S	30E					Eddy

Latitude N 32.154414 Longitude W 103.857821

NATURE OF RELEASE

Type of Release	Produced water and crude oil	Volume of Release: 40 bbls of produced water and 20 bbls of crude oil.	Volume Recovered: 10 bbls total fluid
Source of Release:	Heater Treater	Date and Hour of Occurrence	5/2/11, Hour unknown
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	Date and Hour of Discovery	5/2/11 10:00 a.m.
By Whom?	Tony Savoie	If YES, To Whom?	Mike Bratcher via voicemail
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Date and Hour:	5/2/11 10:51 a.m.
		If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A gasket failed on the heater treater fire tube. During initial response activities, the heater was isolated, and the gasket was replaced.

Describe Area Affected and Cleanup Action Taken.* The caliche pad around the pumping well and tank battery location had isolated packets of produced water and crude oil. The liquid also travelled down a lease road for approximately 360 ft. The entire area of the well pad and battery location was also covered with a fine mist of crude oil and produced water; this was approximately 67,500 sq. ft. The pasture land located to the South West of the battery was also affected with the fine mist of crude oil and produced water; this area was approximately 33,600 sq. ft. The release was remediated as per NMOCD guidelines. Please see the attached *Remediation Summary & Risk-Based Site Closure Request*, dated May 2012, for details of remediation activities and laboratory analytical results from confirmation soil samples.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Ben S. Arguajo Ben S. Arguajo (Agent of BOPCO, LP)	Approved by District Supervisor:	
Title:	Project Manager, Basin Environmental	Approval Date:	9/3/14
E-mail Address:	tasavoie@basspet.com b.s. arguajo@basinenv.com	Expiration Date:	NA
Date:	2/14/13	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	(432) 556-8730 (806) 549-9597		Final 2RP-773

