## **NM OIL CONSERVATION** ARTESIA DISTRICT

State of New Mexico **Energy Minerals and Natural Resources** 

FEB 1 2 2015

Form C-141

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC. **RECEIVED** 

## District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action	
	OPERATOR ☐ Initial Report ☐ Final Report
Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Indian Flats Bass Federal SWD Tank Battery	Facility Type: Exploration and Production
Battery is located 2996 ft. S.W. of Well #1 API 30-015-24968	
Surface Owner: Federal Mineral Own	er: Federal API No. 30-015-24968
LOCATION OF RELEASE	
Unit Letter   Section   Township   Range   Feet from the   No.	rth/South Line   Feet from the   East/West Line   County Eddy
J 35 21S 28E 1652 So	uth 2150 East
Latitude N. 32.433935 Longitude W. 104.055036	
NATURE OF RELEASE	
Type of Release: Produced Water	Volume of Release: 153 Bbls. Volume Recovered: Total 138 Bbls. 110
	bbls from the 0 perm cont. 28 bbls. off
Source of Release: 1" fitting on the SWD pump	the ground.  Date and Hour of Occurrence: Date and Hour of Discovery:
Source of Release. 1 Milling on the 5 W b pump	Date 2/10/14 time unknown  Date 2/10/14 at 9:30 a.m.
Was Immediate Notice Given?	If YES, To Whom? NMOCD Emergency #104
☐ Yes ☐ No ☐ Not Requi	
By Whom? Jody Walters	Date and Hour: 2/10/14 at 3:02 p.m.
Was a Watercourse Reached?  ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.
If a Watercourse was Impacted, Describe Fully.*	
Describe Cause of Problem and Remedial Action Taken.* A one inch fitting on the SWD pump broke during the night. The pump was shut down and the failed fitting was replaced.	
Describe Area Affected and Cleanup Action Taken.*  The SWD pump and tank battery have been fitted with 0 perm containment, the high pressure spray was not completely contained, an area covering approximately 3080 sq.ft. in front of the SWD was impacted by the release.  Basin Environmental began the remediation on 7/11/14 and completed the field activities on 8/28/14. Please reference the soil closure request dated Sept. 2014. This remediation ties into the previous remediation and soil closure request submitted on 10/3/13.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
	OIL CONSERVATION DIVISION
Signature: Que du la companya de la companya del la companya de la	
Printed Name: Tony Savoie	Approved by Environmental Specialist:
Title: Waste Management and Remediation Specialist	Approval Date: 2/17/15 Expiration Date: WA
E-mail Address: tasavoie@basspet.com	Conditions of Approval:
Date: 2/18/14 2/12/15 Phone: 432-556-8730	Tines