District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fc, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

n701504936591

FEB 20 2015

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

			4 4		OPERATOR Initial Report Final R						Final Report		
Name of Company: Mewbourne Oil Company						Contact: Zack Thomas							
Address: PO Box 5270 Hobbs NM 88241						Telephone No. 575-393-5905							
Facility Name: Federal 31 G #005						Facility Type: Producing Oil Well							
Surface Owner: BLM Mineral Owner						DIM	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	API No. 30-025-35851					
TVINCEAL OWNER						. DLW			1 API No. 30-023-33831				
				LOCA	TIO	N OF RE	LEASE						
Unit Letter							h/South Line Feet from the East/\			West Line County			
A	31	198	33E	660'	North		990'	East	Lea				
		<u> </u>						.					
			L	atitude32.622	168	Longitud	e -103.697163	7					
								_					
r- <u></u>				NAT	····	OF RELEASE							
Type of Release: Oil							Volume of Release: estimated 7 Volume Recovered: 3 bbls						
Source of Release: Polly Gas Line						Date and Hour of Occurrence Date				e and Hour of Discovery			
Source of Release. Forly Gas Effic						2-13-15			2-13-15 2:00 pm				
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required						If YES, To Whom?							
						1 Duncan Whitlock							
By Whom? Zack Thomas						Date and Hour 2-16-15 7:30' am							
Was a Watercourse Reached? ☐ Yes ☑ No						If YES, Volume Impacting the Watercourse.							
						[.							
If a Watercourse was Impacted, Describe Fully.*													
		•							WAR.)			
		•						- Ro	~@ ₍			· · · · · · · · · · · · · · · · · · ·	
Describe Cause of Problem and Remedial Action Taken.*													
If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* High line pressure caused poly gas line to rupture. Well was shut-in by pumper to stop release.													
	,	-1-76			• J P			PROS		Ġ.	•		
Describe Are	a Affected	and Cleanup A	Action Tal	cen.*									
A 66- at a d	. C 41- /C			- 4			50 6+ fu11	9 ~ 				2 hhla af	
				n tanks out in the ped off to R360 by T									
				fill will be brough						,	, p. 10 . ș.	io griency	
												·	
				is true and compl									
				nd/or file certain re ce of a C-141 repor									
				investigate and re									
				otance of a C-141 r									
federal, state,	or local lav	ws and/or regi	ulations.										
Signature: 2 Homas Printed Name: Zack Thomas						OIL CONSERVATION DIVISION							
						Approved by Environmental Specialist:							
						Medianis							
1													
Title: Environmental Rep.							Approval Date: 2-1775 Expiration Date: 4/77					5	
E-mail Address: zthomas@mewbourne.com							Conditions of Approval:						
Le triur e la constantia de la constantia del constantia della constantia						Site Sogle Regard. Delin Econolist na par Nonco Sobet fine (-141 by 4-17-1)			Attached 🗆				
Date: 2-16-1:	5		H	hone: 575-602-21	88	E and	de age se	serve		IRP	-39	38	
Attach Addi	tional She	ets If Necess	sary			51		mich	note			14744	
						sovet for	e (-191 by	4-17-18		, -	, _	•	
								*		P 10 1	304	136352	