State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT MAR 0 3 2015 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action OPERATOR Initial Report Final Report Name of Company: BOPCO, L.P. Contact: Tony Savoie Contact: Tony Savoie Contact: Tony Savoie Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Telephone No. 575-887-7329 Exploration and Production Facility Name: Poker Lake Unit #216 Facility Type: Exploration and Production Exploration and Production

Surface Owner: Federal

Mineral Owner: Federal

API No. 30-015-33861

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	17	248	30E					Eddy
			Í					

Latitude\_N 32.21200\_Longitude\_W 103.91197 NATURE OF RELEASE

## Type of Release: Produced water and crude oil Volume of Release: 25 bbls of Volume Recovered: 40 bbls total fluid PW and 25 bbls crude oil Source of Release: Flow line Date and Hour of Discovery: Date and Hour of Occurrence: 3/21/10 Approximately 8:00 p.m. 3/21/10 at 8:30 p.m. Was Immediate Notice Given? If YES, To Whom? Yes 🗌 No 🗌 Not Required NMOCD Emergency #104 "Randy" By Whom? Tony Savoie Date and Hour: 3/22/10 at 12:06 p.m. Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. 🗌 Yes 🖾 No If a Watercourse was Impacted, Describe Fully.\* Describe Cause of Problem and Remedial Action Taken.\* A 2 3/8" flow developed a leak under the caliche road known a Rawhide road, the flow line is a conduit under the road with approximately 20 other flow lines. Crews started shutting in wells and excavating the area to determine the exact well. A vacuum truck was on-site and began recovering oil from the excavated area. The affected line was replaced the same day. Describe Area Affected and Cleanup Action Taken.\* The spill affected approximately 1000 sq.ft. of lease road and approximately 1800 sq. ft. of pasture land. The area in the road was excavated to repair the line, due to the number of lines in the conduit and traffic requirements soil samples were collected from the excavated area in the road and backflilled. The area will be delineated and a remediation plan will be submitted in accordance with the NMOCD recommended guidelines. Basin Environmental Services began the field activities on 11/10/14 and completed the excavation, disposal and replacement of approximately 340 cubic yards of soil on 1/5/15. Please reference the Soil Closure Request dated January 2015. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISIO Signature: Approved by Environmental Specialist: Printed Name: Tony Savoie Title: Waste Management and Remediation Specialist Approval Date: **Expiration Date:** E-mail Address: tasavoie@basspet.com Conditions of Approval: Attached Date: 3/3/2015 Phone: 432-556-8730

\* Attach Additional Sheets If Necessary

2RP-0547