District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

By Whom?

Was a Watercourse Reached?

Christopher Jones

If a Watercourse was Impacted, Describe Fully.*

☐ Yes ☒ No

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

AUG 12 2013

Release Notification and Corrective Action **OPERATOR** Initial Report Final Report Name of Company Oxy Permian Ltd. Contact Christopher Jones 1502 W. Commerce Dr., Carlsbad, NM Telephone No. (575) 628-4121 Address Facility Name Old Ranch Knoll 8 Federal #6 Facility Type Surface Owner BLM Mineral Owner Lease No. API#30-015-32295 LOCATION OF RELEASE Range Feet from the North/South Line Feet from the East/West Line Unit Letter Section Township County **22S** 24E 2120 North G 1600 East Eddy County, NM Latitude N 32.40723° Longitude W 104.51700 NATURE OF RELEASE 70 bbls Type of Release Produced water Volume of Release 100 bbls Volume Recovered Source of Release 3" steel water line from discharge side of 3 phase Date and Hour of Occurrence Date and Hour of Discovery separator 1/15/13 Was Immediate Notice Given? If YES, To Whom? Mike Bratcher- OCD, James Amos-BLM, Terry Gregston-BLM

Date and Hour 1/16/13 @ 7:20 am

If YES, Volume Impacting the Watercourse.

Describe Cause of Problem and Remedial Action Taken.*

A 3" steel water line from the discharge side of the 3 phase separator broke causing 100 bbls of produced water to leak onto the ground. 70 bbls were recovered via vacuum truck. The well is going to be plugged.

Describe Area Affected and Cleanup Action Taken.*

The area affected is approximately 175' x 80'. A 3" steel water line from the discharge side of the 3 phase separator broke causing 100 bbls of produced

water to leak onto the ground. 70 bbls were recovered via vacuum truck. The well is going to be plugged. Remediation was completed in accordance with a remediation plan approved by Mike Bratcher of NMOCD via email on 04/05/2013 and approved by James Amos of the BLM via email on 04/12/2013.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION
Printed Name: Christopher Jones	Approved by District Supervisor:
Title: HES Specialist	Approval Date: 8/27/14 Expiration Date: NA
E-mail Address: Christopher_Jones@oxy.com	Conditions of Approval:
Date: 8-9-13 Phone: (575) 628-4121	final Amazina
Assurb Additional Chasta TCNT	22

* Attach Additional Sheets If Necessary

2KP-1522