


2RP-947

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

Submit to appropriate District Office in accordance with 19.15.29 NMAC

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: LINN Energy	Contact: Joe Hernandez
Address: 2130 W Bender Blvd. - Hobbs, NM	Telephone No.: 575-942-8675
Facility Name: Skelly Unit 199	Facility Type: Single Tank Battery
Surface Owner: BLM	Mineral Owner: BLM
API No.: 3001528972	

#### LOCATION OF RELEASE

Unit Letter N	Section 15	Township 17S	Range 31E	Feet from the 1310	North/South Line FSL	Feet from the 2546	East/West Line FWL	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude: 32°49'51.0" Longitude: -103°51'28.4"

#### NATURE OF RELEASE

Type of Release: Land	Volume of Release: 1	Volume Recovered: 0.5
Source of Release: Produced Water	Date and Hour of Occurrence: 10/28/2011 - 0900	Date and Hour of Discovery: 10/28/2011 - 0930
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: Back pressure valve had trash in it. Trash was cleaned out.		
Describe Area Affected and Cleanup Action Taken.* : 0.5 bbls of fluid were picked up and disposed of. The affected area was around the wellhead. The affected area was excavated and disposed of at Lea Land, then backfilled with clean caliche.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

#### OIL CONSERVATION DIVISION

Signature:	Approved by District Supervisor:	
Printed Name: Jose Hernandez	Approval Date: 2/13/15	Expiration Date: N/A
Title: Foreman	Conditions of Approval: Final	
E-mail Address: jhernandez@linnenergy.com	Attached <input type="checkbox"/>	
Date: 01/30/2013	Phone: 575-738-1739	

\* Attach Additional Sheets If Necessary

2RP-947

## Bratcher, Mike, EMNRD

---

**From:** Theresa McCracken <TMcCracken@linnenergy.com>  
**Sent:** Wednesday, January 30, 2013 7:08 AM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** Skelly Unit 199 Final C-141  
**Attachments:** Skelly Unit 199 Final C-141.pdf

Please see attached.

Thank you,

Theresa

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.