

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

DAB1507030496 OPERATOR Subsequent ☐ Initial Report ☒ Final Report

Name of Company	MATADOR PRODUCTION COMPANY	Contact	Ava Monroe
Address	5400 LBJ Freeway, Ste 1500, Dallas, TX 75240	Telephone No.	972-371-5218
Facility Name	Rustler Breaks 12-24-27	Facility Type	Lease

Surface Owner	Mineral Owner	API No.	30-015-41775
---------------	---------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	12	24S	27E	380	S	330	E	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	Flare - natural gas during sales P/L shut in	Volume of Release	see below	Volume Recovered	0
Source of Release	ICE PLUG AND METER REPAIRS	Date and Hour of Occurrence	3/14	Date and Hour of Discovery	SAME
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	EMAIL TO RANDY DADE		
By Whom?	MARLON MCFARLAIN	Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	NM OIL CONSERVATION ARTESIA DISTRICT		
If a Watercourse was Impacted, Describe Fully.*			MAR 16 2015		
			RECEIVED		
Describe Cause of Problem and Remedial Action Taken.* Gas purchaser (Crestwood) has ice plug in line and sales meter issues which shuts down pipeline. Began flaring intermittently. Repairs in process. This well flared 822 mcf 3/1/15 for P/L issues, 3/14 250 mcf for ice plug in purchaser's line and 3/15 335 mcf for purchaser's meter repairs. <u>already reported</u> (585 mcf)					
Describe Area Affected and Cleanup Action Taken.*					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Ava Monroe</u>		OIL CONSERVATION DIVISION	
Printed Name: Ava Monroe		Approved by Environmental Specialist: <u>H. [Signature]</u>	
Title: Sr. Engineering Technician		Approval Date: <u>3/17/15</u>	Expiration Date: <u>NA</u>
E-mail Address: amonroe@matadorresources.com		Conditions of Approval: <u>FINAL</u>	
Date: 03/16/2015 Phone: 972-371-5218		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2RP-2863