## **NM OIL CONSERVATION**

ARTESIA DISTRICT

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources MAR 2 6 2015

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in RECEIVED accordance with 19.15.29 NMAC.

Release Notification and Corrective Action													
NAB 1509054050						OPERATOR					$\boxtimes$	Final Report	
Name of Company OGRID Number						Contact						3	
						Robert Asher							
Address 104 S. 4 <sup>th</sup> Street						Telephone No. 575-748-1471							
						Facility Type							
Bolivar BRI			Battery										
Surface Own	ner	wner	API No.										
Surface Owner Mineral Owner Federal Federal						30-015-4					0742		
LOCATION OF RELEASE													
						South Line	Feet from the	Vest Line County					
l	33 24S 27E 1030			South 330			East Eddy						
<u> </u>			<u> </u>		<u> </u>			<u></u>	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		·····		
Latitude 32.17173 Longitude 104.18751													
NATURE OF RELEASE													
Type of Release Crude Oil						Volume of Release 20 B/O			Volume Recovered 20 B/O				
Source of Release						Date and Hour of Occurrence			Date and Hour of Discovery				
Production Tank										/12/2015; AM			
Was Immediate Notice Given?  ☐ Yes ☐ No ☐ Not Required						If YES, To Whom?  Mike Bratcher/NMOCD II							
						Date and Hour							
By Whom? Robert Asher/Yates Petroleum Corporation						3/13/2015; AM (Email)							
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.							
			<b>∛</b> No										
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken.*													
While switching tanks, the valve on the full tank was left open while the equalizer was closed, causing the release. Vacuum truck(s) were called.													
Describe Area Affected and Cleanup Action Taken.*  An approximate area of 48'X 8' within the lined and bermed battery. The valves were closed and 100% of the released oil was recovered using a vacuum													
truck. Impacted gravel removed/hauled to a NMOCD approved facility. Depth to Ground Water: < 50 (approximately 25', per ChevronTexaco													
Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 20. Based on the battery being													
lined/bermed all released crude oil recovered, Yates Petroleum Corporation requests closure.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state, or local laws and/or regulations.													
$\bigcirc$ $\bigcirc$ .							OIL CONSERVATION DIVISION						
Signature:			1/ //										
			Approved by Environmental Specialist:										
Printed Nam	e: Robert A	Asher				11-40-0							
Title: NM E	nvironment		Approval Date: 3 31 15 Expiration Date:										
F-mail Add	ece hoho	) ýatespetrolei		Conditions of Ammount									
P-man Vada	233. DUDA(U	- IN A Attached											
Date: March 27, 2015 Phone: 575-748-4217 2RP-													

\* Attach Additional Sheets If Necessary

2RP-292LP

## Patterson, Heather, EMNRD

From:

Tanna Adams <TCAdams@yatespetroleum.com>

Sent:

Friday, March 27, 2015 9:24 AM

To:

Bratcher, Mike, EMNRD

Cc:

Patterson, Heather, EMNRD; Bob Asher; jamos@blm.gov

Subject:

Bolivar BRD Federal Com #1H C141

**Attachments:** 

Bolivar BRD Federal Com #1H\_C141\_InitialFinal\_031215.pdf

Mr. Bratcher,

Please find attached the signed C141 Initial/Final for the below listed location:

Bolivar BRD Federal Com #1H 30-015-40742 Section 33, T24S-R27E 1030 FSL & 330 FEL Eddy County, New Mexico

Thank you,

## Tanna Adams

Yates Petroleum Corporation
Environmental Tech
Environmental Department
TCAdams@yatespetroleum.com

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.