


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NJM *W* *1331048065* OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: Chevron <i>4323</i>	Contact: Bradley Blevins
Address: 1616 West Bender	Telephone No.: (575) 391-1462 Ext. 86424
Facility Name: Lotos 15 Federal #1	Facility Type: Oil well

Surface Owner: BLM	Mineral Owner:	API: 30-015-36064
--------------------	----------------	-------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	15	24S	31E	330	South	330	East	Eddy

Latitude: N 32° 12' 39.68" Longitude: W 103° 45' 29.61"

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 9 bbls	Volume Recovered: 0 bbls
Source of Release: Water hauler dumped produced water on pad	Date and Hour of Occurrence: 10/22/13 @ 12:30pm	Date and Hour of Discovery: 10/22/13 @ 12:30pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Bradley Blevins	Date and Hour: 10/22/13	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
Depth to Water. ~360 ft bgs		
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* Approximately 9 bbls of produced water were released when a water hauler released its load on the well pad. There was no volume recovered. No remedial work has yet commenced on the location.		
Describe Area Affected and Cleanup Action Taken.* Approximately 2,500 square feet of surface area was impacted by the release. No volume of water was recovered from the site. Soil samples were collected from release area and submitted to Cardinal Laboratories for testing. Upon receipt of laboratory analytical data from soil samples collected during delineation operations, EPI will prepare and present a Remediation Proposal for approval.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature:	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by District Supervisor: <i>Mike Bratcher</i>	
Title: HE Specialist	Approval Date: NOV 06 2013	Expiration Date:
E-mail Address: bradley.blevins@chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

December 6, 2013

2RP-2046