

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**RECEIVED**  
OCT 03 2013  
NMOCD ARTESIA

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**  Initial Report  Final Report

Name of Company	Apache Corporation	Contact	Bruce Baker
Address	PO BOX 1849, Eunice, NM 88231	Telephone No.	(575) 394-1503
Facility Name	NB Tween #029	Facility Type	Production Well
Surface Owner	State	Mineral Owner	Unknown
		API No.	30-015-39747

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	25	17S	28E	1525	FNL	1670	FEL	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Brine	Volume of Release	20 bbls	Volume Recovered	0 bbls
Source of Release	Overfilled frac tanks	Date and Hour of Occurrence	3/23/2012 0300	Date and Hour of Discovery	3/23/2012 0300
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

**RECEIVED**  
OCT 03 2013  
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Transport driver fell asleep while unloaded his truck into the frac tanks on location, when the tanks overflowed onto the location pad.

Describe Area Affected and Cleanup Action Taken.\*  
The leak affected the caliche pad surrounding the wellhead. The impacted areas were excavated to 1 ft. below ground surface. Representative grab samples were collected from the excavation, field tested, and sent to a commercial laboratory for chloride analysis. Impacted soils were removed to a NMOCD approved disposal facility. The excavations were backfilled with clean imported caliche and leveled.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Bruce Baker		Approved by District Supervisor: <i>[Signature]</i>	
Title: <i>environmental Tech</i>		Approval Date: <i>4/20/15</i>	Expiration Date: <i>NA</i>
E-mail Address: <i>larry.baker@apachecorp.com</i>		Conditions of Approval: <i>Final</i>	
Date: <i>8-30-13</i>	Phone: (575) 394-1503	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

*22P-1098*