## **Bratcher, Mike, EMNRD**

From:

Cliff P. Brunson <cbrunson@bbcinternational.com>

Sent:

Tuesday, September 11, 2012 8:25 PM

To:

Bratcher, Mike, EMNRD

Cc:

Chris Jones; Ken Swinney; Kathy Purvis; Jennifer Gilkey

Subject:

FW: MH Fed Com #1 N SWD

**Attachments:** 

Remediation Packet- MH Fed Com #1 N SWD - 2.pdf

Mike,

I noticed that I left out your request for a confirmation sample. After excavation, Oxy will collect a confirmation sample to be analyzed for TPH and BTEX and this data will be submitted to the NMOCD for your files.

Thanks, Cliff

Cliff P. Brunson, CEI, CRS
President
BBC International, Inc.
World-Wide Environmental Specialists
Mailing Address:
P. O. Box 805
Hobbs, NM 88241-0805 USA
Shipping Address:
1324 W. Marland St.
Hobbs, NM 88240 USA
Phone: (575) 397-6388
Fax: (575) 397-0397

E-Mail: cbrunson@bbcinternational.com

Confidentiality Notice: This electronic transmission (and any attached documents) is intended only for the person(s) to whom it is addressed and may contain information that is privileged, confidential, or otherwise protected from disclosure. If you have received this transmission in error, please immediately notify the sender by e-mail or by telephone call to (575) 397-6388 for handling instructions. Any disclosure or distribution of the contents of this transmission by anyone other than the named recipient(s) is strictly prohibited.

\*\*\*\*\*\*\*\*\*\*\*\*

\*\*\*\*\*\*\*\*\*\*\*\*\*

From: Cliff Brunson < cbrunson@bbcinternational.com>

**Date:** Tuesday, September 11, 2012 6:47 PM **To:** Mike Bratcher <mike.bratcher@state.nm.us>

Cc: Chris Jones < Christopher Jones@oxy.com>, Ken Swinney < kswinney@bbcinternational.com>, Kathy Purvis

< kathy@bbcinternational.com >, Jennifer Gilkey < jgilkey@bbcinternational.com >

Subject: MH Fed Com #1 N SWD

Mike,

This e-mail is to confirm our discussion on September 5, 2012 concerning the remediation plan for the release that occurred at the Oxy MH Fed Com #1 N SWD. As agreed, Oxy will excavate to a depth of 1 foot across the entire spill area as depicted on the attached site diagram. The excavation will then be backfilled with clean soil. The depth to groundwater is this area is approximately 50 feet.

I have attached the site drawing and the summary of the laboratory data we reviewed during our discussion for your files. If you would please reply back via e-mail with your concurrence of this remediation plan, it would be greatly appreciated.

Oxy and I thank you for your assistance in handling this matter.

## Thanks, Cliff

Cliff P. Brunson, CEI, CRS
President
BBC International, Inc.
World-Wide Environmental Specialists
Mailing Address:
P. O. Box 805
Hobbs, NM 88241-0805 USA
Shipping Address:
1324 W. Marland St.
Hobbs, NM 88240 USA
Phone: (575) 397-6388

Fax: (575) 397-0397 E-Mail: <a href="mailto:cbrunson@bbcinternational.com">cbrunson@bbcinternational.com</a>

Confidentiality Notice: This electronic transmission (and any attached documents) is intended only for the person(s) to whom it is addressed and may contain information that is privileged, confidential, or otherwise protected from disclosure. If you have received this transmission in error, please immediately notify the sender by e-mail or by telephone call to (575) 397-6388 for handling instructions. Any disclosure or distribution of the contents of this transmission by anyone other than the named recipient(s) is strictly prohibited.

\*\*\*\*\*\*\*\*\*\*\*\*\*