

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT
APR 22 2015
RECEIVED

Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1511729624 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production Company 6137	Contact Garry Michael; Production Foreman	
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-513-4895	
Facility Name Cotton Draw Unit 172H	Facility Type Oil Well	
Surface Owner Federal	Mineral Owner Federal	API No 30-015-42426

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	I	25S	31E	195	South	1345	East	Eddy

Latitude: N 32° 09' 09.41"

Longitude: W 103° 43' 38.37"

NATURE OF RELEASE

Type of Release oil release at the LACT Load line	Volume of Release 64BBLS	Volume Recovered 30 BBLS
Source of Release At the LACT load line	Date and Hour of Occurrence April 15, 2015 6:45 AM	Date and Hour of Discovery April 15, 2015 6:45 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher; OCD & Jim Amos; BLM	
By Whom? David Washington; Assistant Production Foreman	Date and Hour April 15, 2015 12:40PM & April 17, 2015 3:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.
N/A

Describe Cause of Problem and Remedial Action Taken.*

Truck driver allowed truck to overflow while collecting an oil load from the LACT unit. LACT unit was turned off upon discovery of the release preventing more oil from being released.

Describe Area Affected and Cleanup Action Taken.*

64 BBLS of oil was released. All oil released remained on location. Size of the affected area is approximately 350'x 50'. 30BBLS of oil was recovered via vacuum truck. Affected soil was treated in place by Enviroclean Services.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sandy Farley</i>		OIL CONSERVATION DIVISION	
Printed Name: Sandy Farley		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support		Approval Date: 4/27/15	Expiration Date: N/A
E-mail Address: sandy.farley@dvn.com		Conditions of Approval:	
Date: 4/22/15 Phone: 575.746.5587		Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 5/27/15	

* Attach Additional Sheets If Necessary

Attached ☐

2RP-2966

Patterson, Heather, EMNRD

From: Farley, Sandy <Sandy.Farley@dvn.com>
Sent: Wednesday, April 22, 2015 4:11 PM
To: Sol Hughes (shughes@blm.gov); Jim Amos (jamos@blm.gov); Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Jeff Robertson (jlr Robertson@blm.gov); Harris, Jacqui; Marquez, Jeannette; Sanchez, Jessica
Subject: RE: Cotton Draw Unit 172H 65BBLS Oil Spill 4.15.15- Error- 64BBLS oil released
Attachments: Cotton Draw Unit 172H 64BBLS Oil Spill 4.15.15 Initial C-141.doc

Good afternoon,

My apologies,

The original paperwork I submitted stated that 65BBLS of oil was released at the Cotton Draw Unit 172H on April 15, 2015. My documentation was incorrect; it was only 64BBLS of oil released. Attached is an amended C-141 for your records.

Apologies for my error and have a spectacular day

Sandra Farley

Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, New Mexico 88211
575 746 5587


devon

From: Farley, Sandy
Sent: Friday, April 17, 2015 3:31 PM
To: Sol Hughes (shughes@blm.gov); Jim Amos (jamos@blm.gov); Mike Bratcher (mike.bratcher@state.nm.us)- OCD
Eddy County; Patterson, Heather, EMNRD
Cc: Jeff Robertson (jlr Robertson@blm.gov); Harris, Jacqui
Subject: Cotton Draw Unit 172H 65BBLS Oil Spill 4.15.15

Good afternoon,

Attached is the Initial C-141, GIS Image and Photos for the 65BBLS release that occurred at the Cotton Draw Unit 172H on April 15, 2015. The pink dot on the GIS Image represents the approximate location of the release. The yellow box marks the approximate location of the facility as the Image for the facility was not showing up as of yet on GIS Imaging.

Have a wonderful weekend

Sandra Farley

Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, New Mexico 88211
575 746 5587



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.