NM OIL CONSERVATION

District I
1625 N, French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 APR 2 2 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

			Rele	ase Notific		and Co		ction			***************************************	•	
nABI5	1173	8138	•		OPERAT		☐ Initial Report ☐ Final Report						
Name of Company						Contact							
Yates Petroleu Address	ım Corp	oration	15675		Chase Settle								
104 S. 4 th Stre	et				Telephone No. 575-748-1471								
Facility Name					Facility Type								
Mimosa Feder	ral SWD	#4		I	Battery								
Surface Owne	ir,		Mineral C	wner			API No.						
Federal				Federal					30-015-26950				
	LOCATION OF RELEASE												
									West Line County				
ly ly	N 4 20S 24E 660			000	;	South 1980			West Eddy				
	 1			Latitude 32.	59735	Longitude	-104.59513						
NATURE OF RELEASE													
Type of Release					Volume of Release			Volume Recovered					
Produced Water Source of Release						230 B/PW Date and Hour of Occurrence			210 B/PV Date and	<u> </u>	COVET	<i>.</i>	
Production tank	(······································	4/9/2015; AM			Date and Hour of Discovery 4/9/2015; AM						
Was Immediate	Notice (] No ⊠ Not R	emirad	If YES, To Whom? Mike Bratcher, Heather Patterson, Randy Dade, Jim Amos								
By Whom?		<u> </u>	1 100 L	110 21 11011	equired	Date and Hour							
Robert Asher/Y	ates Petr	oleum Corpo		4/9/2015; 5:09 PM									
Was a Waterco	urse Read	ched?		If YES, Volume Impacting the Watercourse.									
If a Watercours	an wing Inc												
If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.*													
The power supply was interrupted, causing the pumps not to start and the tanks to overflow. Vacuum truck(s) were called. Describe Area Affected and Cleanup Action Taken.*													
				ken.* north of the batte	rv string.	and an appr	oximate area of 5	7' X 37'	was affect	ted east of th	ne batt	erv string	
within the bern	ned batter	ry. Called an	electrician	to restore power	to the pu	mps,:a contr	actor to fix the wa	arning al	arms; vacu	um truck to	remov	e standing	
				. Excavated soils C(chlorides for do									
will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 0) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be													
				er: >100' (appro , SITE RANKIN		7360', Section	on 4, T20S-R24E	, per Ti	end Map)	, Wellhead	Protec	ction Area:	
I hereby certify	y that the	information g	given abov	e is true and com	plete to t								
	regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability												
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
or the environment federal, state, or				ptance of a C-14	report d	loes not relie	ve the operator of	f respons	ibility for	compliance	with a	ny other	
	//2	a		OIL CONSERVATION DIVISION									
Signature: منتسر		5											
E. J.				Approved by Environmental Specialist:									
Printed Name:	Chase Se	ettle		The state of the s									
Title: NM Env	dronment		Approval Date: 4 21 5 Expiration Date:										
E-mail Address: CSettle@yatespetroleum.com Conditions of Approval: Remadiation per O.C.D. Rules & Guidelines Phone: 575-748-411 lay 1-28-8-1-1-28-8-1-1-28-8-1-1-1-1-1-1-1-1													
Date: April 22	. 2015			Phone: 575-748-	Rdi Heditali	nediati on 288	per O.C.D. R //EDIATION P	lules &	k Guidel	ines	۔ ∟		
* Attach Additi	ional Sho	ects If Neces	sary			TER THAN		nurl 10	in Jac	<i>J</i>	1	RP-296'	

Patterson, Heather, EMNRD

From:

Tanna Adams <TCAdams@yatespetroleum.com>

Sent:

Wednesday, April 22, 2015 1:10 PM

To:

Bratcher, Mike, EMNRD

Cc:

Patterson, Heather, EMNRD; jamos@blm.gov; Bob Asher; Katie Parker; Chase Settle

Subject:

Mimosa Federal SWD #4

Attachments:

Mimosa Federal SWD #4_C141_Initial_040915.pdf

Mr. Bratcher,

Please find attached the signed C141 Initial for the below listed location:

Mimosa Federal SWD #4 30-015-26950 Section 4, T20S-R24E 660 FSL & 1980 FWL Eddy County, New Mexico

.Thanks,

Tanna Adams

Yates Petroleum Corporation Environmental Tech Environmental Department TCAdams@yatespetroleum.com

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.