NM OIL CONSERVATION ARTESIA DISTRICT

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division

1220 South St. Francis Dr.

Form C-141 Revised August 8, 2011

APR **2 4** 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Santa Fe, NM 87505 Release Notification and Corrective Action nAB1511748740 **OPERATOR** Initial Report Final Report Name of Company Lime Rock Resources II-A, L.P. 27755 Contact Michael Barrett Address 1111 Bagby St. Ste. 4600, Houston, TX 77002 Telephone No. 575-623-8424 Facility Name Windfohr 4 Federal #012 Facility Type Water Transfer Line Surface Owner BLM Mineral Owner Federal API No. 30-015-42037 LOCATION OF RELEASE Range Unit Letter Section Township Feet from the North/South Line Feet from the East/West Line County 128 27E 2005 Eddy Latitude 32.77847 Longitude -104.27121 NATURE OF RELEASE Type of Release Produced water Volume of Release 18bbls Volume Recovered 2bbls Source of Release Date and Hour of Occurrence Date and Hour of Discovery Water Transfer Line 4/8/2015 7:00am 4/8/2015 Was Immediate Notice Given? If YES, To Whom? ☐ Yes ☐ No ☒ Not Required By Whom? Date and Hour If YES, Volume Impacting the Watercourse. Was a Watercourse Reached? ☐ Yes ⊠ No If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* A temporary 12" transfer line had a leak at one of the connections which caused a release of approximately 18bbls of treated produced water. When the leak was discovered the line was repaired and a vacuum truck was dispatched to recover the standing fluid. Approximately 2bbls of fluid were recovered. Talon/LPE mobilized personnel to conduct an initial site assessment and perform soil sampling activities within the impacted area. Describe Area Affected and Cleanup Action Taken.* The impacted area is in the pasture just north of the Apache Red Lake 3 Fed #2 (30-015-29802) location and measures approximately 120' x 50'. Talon/LPE mobilized personnel to conduct an initial site assessment and soil sampling utilizing a hand auger. Refusal with the hand auger was encountered at depths varying from 0.75' to 1' deep. A backhoe was mobilized to continue the vertical delineation of chlorides. Refusal with the backhoe was encountered at a depth of 2' deep. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Approved by Environmental Specialist: Printed Name: Michael Barrett Approval Date: **Expiration Date:** Title: Production Supervisor E-mail Address: mbarrett@limerockresources.com Conditions of Approval: Remediation per O.C.D. Rules & Guidelines 4-23-15 **SUBMIT REMEDIATION PROPOSAL NO** Phone: 575-623-8424 LATER THAN: 5 Attach Additional Sheets If Necessary 2RP-20108

Patterson, Heather, EMNRD

From: Sheldon Hitchcock <slhitchcock@talonlpe.com>

Sent: Friday, April 24, 2015 5:43 PM **To:** Patterson, Heather, EMNRD

Cc: Bratcher, Mike, EMNRD; Robertson, Jeffery; mbarrett@limerockresources.com; David

Adkins

Subject: Lime Rock-Windfohr 4 Federal #012 Water Transfer Line Initial C-141(30-015-42037)

Attachments: 0072_001.pdf

All,

Please see the attached initial C-141 for the Lime Rock Windfohr 4 Fed #12 water transfer line release. This release did not occur on the Windfohr 4 Fed #12 location, it was in the pasture directly north of the Apache Red Lake 3 Fed #2. Please let me know if you have any questions or concerns.

Respectfully,

Sheldon L. Hitchcock

Project Manager Talon/LPE 408 West Texas Avenue Artesia, New Mexico 88210

Phone: (575) 746-8768 Cell: (575) 689-5198 Fax: (575) 746-8905

Email: slhitchcock@talonlpe.com

Web: www.talonipe.com



Better Business Bureau Torch Award for Marketplace Ethics: 2010 Winner, 2009 Finalist

Staples Foundation for Learning Hall of Fame Recipient: 2010 ICIC and Business Week- Top 100: 2010, 2009, 2008, 2007, 2006

Inc. 500/5000: 2012, 2011, 2010, 2009, 2008, 2007

This email and any files transmitted with it are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the system manager. This message contains confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this e-mail. Please notify the sender immediately by e-mail if you have received this e-mail by mistake and delete this e-mail from your system. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited.