

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

~~HOBBS~~ State of New Mexico  
Energy Minerals and Natural Resources  
~~APR 30 2015~~ Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505  
**RECEIVED**

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: <b>OXY USA INC</b>	Contact: <b>Chris Jones</b>
Address: <b>102 S. Main St. Carlsbad, NM 88220</b>	Telephone No.: <b>575-628-4121</b>
Facility Name: <b>Red Tank 35 Federal #3 SWD</b>	Facility Type: <b>SWD</b>

Surface Owner: <b>Federal</b>	Mineral Owner:	API No.: <b>30-025-33149</b> Lease No.: <b>NM-86150</b>
-------------------------------	----------------	--

### LOCATION OF RELEASE

Unit Letter <b>L</b>	Section <b>35</b>	Township <b>22S</b>	Range <b>32E</b>	Feet from the <b>2310'</b>	North/South Line <b>South</b>	Feet from the <b>990'</b>	East/West Line <b>West</b>	County <b>Lea</b>
-------------------------	----------------------	------------------------	---------------------	-------------------------------	----------------------------------	------------------------------	-------------------------------	----------------------

Latitude **32.3479 N** Longitude **-103.65079 W**

### NATURE OF RELEASE


Type of Release: <b>Produced Water</b>	Volume of Release: <b>5 bbls</b>	Volume Recovered: <b>0 bbls</b>
Source of Release: <b>Triplex Pump Malfunctioned</b>	Date and Hour of Occurrence <b>4/15/2015</b>	Date and Hour of Discovery <b>4/15/2015 @ 9:00 am</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? <b>Kimberly M. Wilson</b>	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
---

Describe Cause of Problem and Remedial Action Taken: <b>The plunger on the north triplex pump broke causing a release of 5 barrels of produced water inside the containment of the facility. A vac truck was immediately called to the location and it is unknown how much fluids were recovered.</b>
---

Describe Area Affected and Cleanup Action Taken.* <input type="checkbox"/> The impacted area was inside the containment of the facility. Talon/LPE was contracted to perform initial site assessment and soil sampling activities. The remediation of this release will be addressed in the Remediation Work Plan for the release that occurred March 22, 2015.
---

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<b>Chris</b> Digitally signed by Chris Jones DN: cn=Chris Jones, o, ou, email=cljones888@yahoo.com, c=US Date: 2015.04.28 15:46:15 -0500 Signature: <b>Jones</b>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Chris Jones</b>	Approved by Environmental Specialist: 	
Title: <b>HES Specialist</b>	Approval Date: <b>05/01/2015</b>	Expiration Date: <b>08/01/2015</b>
E-mail Address: <b>Christopher.Jones@oxy.com</b>	Conditions of Approval: <b>- Site samples required</b>	Attached <input type="checkbox"/> <b>16696</b> <b>1KP-3625</b>
Date: <b>3/27/2015</b> Phone: <b>575-628-4121</b>		

\* Attach Additional Sheets If Necessary

- Delinquent and Remedial as  
per NMOCD guidelines.  
- Geotag photographs of  
remediation required.

PKJ 1512135737  
WKJ 1512134515