

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Federal 12-1 South Battery	Facility Type	Gathering

Surface Owner	BLM	Mineral Owner		Lease No.	30-015-26742
---------------	-----	---------------	--	-----------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	12	22S	31E					Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Oil and produced water	Volume of Release	3 bbls of oil and 100 bbls of produced water	Volume Recovered	80 bbls
Source of Release	Pump failure	Date and Hour of Occurrence	11/02/2011	Date and Hour of Discovery	

Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD; James Amos-BLM
-----------------------------	---	------------------	-----------------------------------

By Whom?	Dusty Wilson	Date and Hour	11/03/2011 @ 1:13 pm
----------	--------------	---------------	----------------------

Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
----------------------------	---	---	--

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

SEP 27 2013

NMOCD ARTESIA


Describe Cause of Problem and Remedial Action Taken.\*

Pump failure caused 3 bbls of oil and 100 bbls of produced water to leak onto the ground. A vacuum truck recovered the remaining fluids, 80 bbls total. The pump was repaired.

Describe Area Affected and Cleanup Action Taken.\*

The area affected is approximately 100' x 50'. A vacuum truck recovered 80 bbls. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 11/15/2012 and approved by James Amos of the BLM via email on 12/17/12.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Chancey Summers	Approved by District Supervisor:		
Title: HES Specialist	Approval Date: 5/4/15	Expiration Date:	N/A
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 9/26/13	Phone: (575) 397-8216	Final	

\* Attach Additional Sheets If Necessary

2RP-1404