

# NM OIL CONSERVATION

ARTESIA DISTRICT

State of New Mexico  
Energy Minerals and Natural Resources

MAY 13 2015

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.  
**RECEIVED**

## Release Notification and Corrective Action

**nAB1513456865** **229137** **OPERATOR** ☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Really Scary Federal Com #3	Facility Type: Battery



Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-36372
------------------------	------------------------	----------------------

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	33	24S	28E	430	South	2310'	West	Eddy

Latitude 32.1677297936141 Longitude -104.093479546577

## NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 25 bbls Oil	Volume Recovered: 23 bbls Oil
Source of Release: Over run tank	Date and Hour of Occurrence: 3/29/2015 9:00 am	Date and Hour of Discovery: 3/29/2015 9:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* This release was caused when a valve was left closed. Vacuum trucks were dispatched to recover all standing fluid.		
Describe Area Affected and Cleanup Action Taken.* This release remained within the lined facility and was able to be recovered and the facility put back into production.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 5/14/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: May 1, 2015	Phone: 575-748-6940	

\* Attach Additional Sheets If Necessary

2RP-3004

## **Patterson, Heather, EMNRD**

---

**From:** Amanda Trujillo <ATrujillo@concho.com>  
**Sent:** Wednesday, May 13, 2015 5:56 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; James Amos; 'Robertson, Jeffery'  
**Subject:** (Notification/C-141 Initial-Final) Really Scary Federal Com #3 (30-015-36372)  
**Attachments:** 3-29-2015 Really Scary Federal Com #3 (TB) Initial-Final.pdf

Mr. Bratcher,

COG Operating LLC is reporting a release on the Really Scary Federal Com #3 (30-015-36372)  
Unit N Section 33 Township 24S Range 28E  
The release occurred at 9:00 am on 3/29/2015  
Released: 30 bbls PW  
Recovered: 28 bbls PW

This release was caused when a valve was left closed. Vacuum trucks were dispatched to recover all standing fluid. This release remained within the lined facility and was able to be recovered and the facility put back into production. If you have any additional questions please feel free to contact me.

Thank you,

### **Amanda Trujillo**

Senior Environmental Coordinator  
COG Operating LLC  
Cell: 505.350.1336  
Office: 575.748.6930  
[atrujillo@concho.com](mailto:atrujillo@concho.com)

2407 Pecos Ave.  
Artesia, NM 88210



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.