

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

SEP 19 2013

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Lime Rock Resources II-A, L.P.	Contact	Michael Barrett
Address	P.O. Box 2147, Roswell, New Mexico	Telephone No.	(575) 623-8424
Facility Name	Hondo Federal #001	Facility Type	Tank Battery

Surface Owner: Unknown	Mineral: Federal	Lease No. (API#)30-015-00772
------------------------	------------------	------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	04	18S	27E	2190'	North	1650'	East	Eddy

Latitude N32.77687° Longitude W104.27969°

NATURE OF RELEASE

Type of Release: Oil	Volume of Release 54 bbls Oil	Volume Recovered 24 bbls Oil
Source of Release: Oil Transport Ran Over	Date and Hour of Occurrence 06/24/2013	Date and Hour of Discovery 06/24/2013 2:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Michael Barrett	Date and Hour 06/24/2013 2:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\* N/A



Describe Cause of Problem and Remedial Action Taken.\*

TIGA transport (Oxy) over ran tanker while picking up a load of oil.

Describe Area Affected and Cleanup Action Taken.\*

Tetra Tech personnel inspected the site and collected samples to define the spill extents. Soil that exceeded the RRAL was removed and hauled away for proper disposal. The site was then brought up to surface grade with clean backfill material. Tetra Tech prepared a closure report and submitted it to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez (agent for Lime Rock)	Approved by District Supervisor: 	
Title: Project Manager	Approval Date: 5/11/15	Expiration Date: N/A
E-mail Address: Ike.Tavarez@tetratech.com	Conditions of Approval: 2RP-1702	Attached <input type="checkbox"/>
Date: 8-27-13	Phone: (432) 682-4559	

\* Attach Additional Sheets If Necessary