

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nABI515455677 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: LRE Operating, LLC. 381994	Contact: Mike Barrett
Address: 1111 Bagby Street Suite 4600, Houston, TX 77002	Telephone No.: 575-623-8424
Facility Name: Marathon 25 State #8	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API #30-015-29967
----------------------	----------------	-------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	25	17S	28E	990'	FNL	1650'	FWL	Eddy

Latitude 32.8122139954 N Longitude -104.133053542 W

NATURE OF RELEASE



Type of Release: Oil	Volume of Release: 103 bbl Oil	Volume Recovered: 97 bbls Oil
Source of Release: Valve Malfunction	Date and Hour of Occurrence: 5/14/15 4:00 pm	Date and Hour of Discovery: 4/14/15 4:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD * Heather Patterson via phone @ 10:45 am	
By Whom? Kimberly Wilson with Talon/LPE	Date and Hour: 5/15/15 @ 10:45 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A valve malfunctioned inside the facility causing the release of 103 barrels of oil. A vac truck was immediately called to the location and recovered 97 barrels of oil. All wells were shut in, the valve was replaced and the facility was brought back into service. The release stayed within the berm of the facility. No fluids breached the berms of the facility.

Describe Area Affected and Cleanup Action Taken.* Talon/LPE was on site on May 15, 2015 for the initial site assessment activities. Hydrovac operations are in progress May 15, 2015. A work plan will be generated.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Michael Barrett	Approved by District Supervisor: 	
Title: Production Supervisor	Approval Date: 6/18/15	Expiration Date: N/A
E-mail Address: mbarrett@limerockresources.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 7/19/15	
Date: 5/18/2015 Phone: 575-623-8424	2RP-3038	

* Attach Additional Sheets If Necessary

NM OIL CONSERVATION
ARTESIA DISTRICT

JUN 8 2015

RECEIVED

Patterson, Heather, EMNRD

From: Kimberly M. Wilson <kwilson@talonlpe.com>
Sent: Monday, June 08, 2015 2:11 PM
To: Patterson, Heather, EMNRD
Cc: Michael Barrett; David Adkins; Sheldon Hitchcock
Subject: Lime Rock-Marathon 25 State #8 CTB Work Plan (30-015-29967
Attachments: Marathon 25 State C-141 (signed).pdf

Heather attached please find the signed C-141 for the above referenced release.

Thanks Kim

Kimberly M. Wilson

Project Manager
Talon/LPE
408 West Texas Avenue
Artesia, New Mexico 88210
Office: 575.746.8768
Fax: 575.746.8905
Cell: 575.602.3826
Emergency: 866.742.0742
Email: kwilson@talonlpe.com
Web: www.talonlpe.com



Better Business Bureau Torch Award for Marketplace Ethics: 2010 Winner, 2009 Finalist
Staples Foundation for Learning Hall of Fame Recipient: 2010
ICIC and Business Week- Top 100: 2010, 2009, 2008, 2007, 2006
Inc. 500/5000: 2012, 2011, 2010, 2009, 2008, 2007