

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

<u>NAB1516753239</u>		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Devon Energy Production <u>6137</u>		Contact Randy Gladden			
Address 6488 Seven Rivers Hwy Artesia, NM 88220		Telephone No. 575.513.9463			
Facility Name Todd 24-B Battery 2		Facility Type OIL			
Surface Owner BLM		Mineral Owner BLM		API No. 30-015-27691	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	24	23S	31E	660	North	1980	East	EDDY

Latitude: 32.29523 Longitude: -103.72888

NATURE OF RELEASE

Type of Release Spill Produced Water	Volume of Release 80 BBL	Volume Recovered 75 BBL
Source of Release A water transfer pump went down causing water tank to overflow.	Date and Hour of Occurrence 2.23.15 4:00 am	Date and Hour of Discovery 2.23.15 11:10 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson BLM Mike Bratcher OCD	NM OIL CONSERVATION ARTESIA DISTRICT JUN 15 2015
By Whom? Randy Gladden	Date and Hour 2.23.15 @ 11:20 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	RECEIVED
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Result of transfer pump not operating properly approximately 80 barrels of produced water spilled inside containment. Lobo trucking recovered 75 BBLS and the transfer pump was repaired and returned to normal operations.		
Describe Area Affected and Cleanup Action Taken.* Unlined Containment 15x80 all inside containment. Environmental service will be called on.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <u>Jeanette Barron</u>	OIL CONSERVATION DIVISION	
Printed Name: Jeanette Barron	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Field Admin Support	Approval Date: <u>6/16/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: Jeanette.barron@dmv.com	Conditions of Approval:	
Date: 2.26.15 Phone: 575.748.1813	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>7/17/15</u>	

* Attach Additional Sheets If Necessary

2RP-3051

Patterson, Heather, EMNRD

From: Rebecca Pons <office2@sesi-nm.com>
Sent: Monday, June 15, 2015 3:06 PM
To: Patterson, Heather, EMNRD
Subject: 30-015-27691 Todd 24-B Battery 2
Attachments: C-141 Todd 24 B 2 Spill.doc

Good afternoon,

I have attached the C-141 associated with the spill on the above location. Upon reviewing the NMOCD website I have noticed that are two other open C-141's for this site 2RP-1391 and 2RP-1686 respectively. Please advise me on how you would prefer that I proceed. If necessary, we can remediate for all spills at one time. Also, please advise me on the RP number for this spill.

Have a great evening,

Thank You

Rebecca Pons

Saftey & Environmental Solutions, Inc.
703 East Clinton Street
Hobbs, NM 88240
Office: (575) 397-0510