

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1518050116		OPERATOR	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Name of Company Yates Petroleum Corporation	25575	Contact Amber Cannon	NM OIL CONSERVATION ARTESIA DISTRICT JUN 24 2015 RECEIVED
Address 104 S. 4 th Street		Telephone No. 575-748-1471	
Facility Name Livingston Ridge SWD Water Line (Wolf AJA Federal Com # 17H)		Facility Type Water Transfer Line	
Surface Owner Federal	Mineral Owner Federal	API No. 30-015-39829	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	25	21S	31E	1920	North	300	East	Eddy

Latitude 32.455771 Longitude 103.725007

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 50 B/PW	Volume Recovered 0 B/PW
Source of Release Poly line	Date and Hour of Occurrence 6/18/2015; AM	Date and Hour of Discovery 6/18/2015; PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson, Randy Dade, & Jim Amos	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 6/19/2015; AM (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A water poly line split, causing the release. Vacuum truck(s) and roustabout crews were called. The wells were shut in and vacuum trucks were called to recover the spill, but no released produced water was recovered. A roustabout crew was called to repair the poly line.

Describe Area Affected and Cleanup Action Taken.*

An approximate total area of 0.6272 acres, with a pooling area of 0.0490 acres and an overspray area of 0.5782 acres. The overspray area will be treated with a 3% microblaze solution, and the pooling area will have vertical and horizontal delineation samples taken and analysis ran for TPH & BTEX (chlorides for documentation). Excavated soils will be hauled to a NMOCD approved facility. If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 0) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. Depth to Ground Water: >100' (approximately 125', Section 25, T21S-R31E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Amber Cannon</u>	OIL CONSERVATION DIVISION	
Printed Name: Amber Cannon	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: NM Environmental Regulatory Agent	Approval Date: <u>6/29/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: ACannon@yatespetroleum.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 24, 2015	Phone: 575-748-4111	

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 7/30/15

2RP-3074

Patterson, Heather, EMNRD

From: Tanna Adams <TCAAdams@yatespetroleum.com>
Sent: Wednesday, June 24, 2015 10:26 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD; jamos@blm.gov
Cc: Bob Asher; Amber Cannon; Chase Settle; Katie Parker; Veronica Alvarado
Subject: Livingston Ridge SWD Water Line (Wolf AJA Federal Com #17H) C141
Attachments: Livingston Ridge SWD Water Line (Wolf AJA Federal Com #17H)_C141_Initial_061815.pdf

Good morning,

Please find attached the signed C141 Initial for the below listed location:

Livingston Ridge SWD Water Line
(Wolf AJA Federal Com #17H)
30-015-39829
Section 25, T21S-R31E
1920 FNL & 300 FEL
Eddy County, New Mexico

Thank you,

Tanna Adams

Yates Petroleum Corporation

Environmental Tech

Environmental Department

TCAAdams@yatespetroleum.com

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
