

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

1 AB1523/55412		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P.		Contact: Amy Ruth			
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329			
Facility Name: Indian Flats Bass Federal SWD (SWD is located 2996 ft. SW of Well #1 Apl 30-015-24968)		Facility Type: Exploration and Production			
Surface Owner: Federal		Mineral Owner: Federal		API No. 30-015-24968	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	35	21S	28E	1652	South	2150	East	Eddy

Latitude 32.433935° Longitude -104.055036°

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 8 bbls	Volume Recovered 1 bbls
Source of Release 1/2" fitting on SWD pump	Date and Hour of Occurrence 8/13/2015 unknown time	Date and Hour of Discovery 8/13/2015 10:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*



A 1/2" inch fitting on the discharge side of the east SWD pump failed. Pump shut down and fitting was repaired.

Describe Area Affected and Cleanup Action Taken.\*

The leak affected approximately 3,058 square ft. area of caliche pad directly south of the SWD containment and surrounding containment on all sides. A vac truck recovered fluids from the zero perm containment as well as from the ground. The leak on the caliche is within an area previously lined with 20-mil plastic. The saturated surface soils were scraped up and removed to a NMOCD approved disposal facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Amy Ruth	Approval Date: 8/19/15	Expiration Date: N/A
Title: Assistant Remediation Foreman	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
E-mail Address: ACRuth@basspet.com	Attached <input type="checkbox"/>	
Date: 8/17/2015	Phone: 432-661-0571	

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 9/21/15

\* Attach Additional Sheets If Necessary

2RP-3212

## **Patterson, Heather, EMNRD**

---

**From:** Ruth, Amy C. <ACRuth@BassPet.Com>  
**Sent:** Monday, August 17, 2015 2:37 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Cc:** jamos@blm.gov  
**Subject:** Initial C-141 Indian Flats Bass Federal SWD leak on 8-13-2015  
**Attachments:** Initial C-141 Indian Flats Bass Federal SWD 8-13-15.pdf

Here is another C-141 for this site within a week. Leak was from the other pump this time.



*Amy C. Ruth*  
BOPCO, L.P.  
EH&S Remediation Specialist  
522 W. Mermod, Suite 704  
Carlsbad, NM 88220  
Office: (575)887-7329  
Fax: (575)887-7473  
Cell: (432)661-0571