NM OIL CONSERVATION

ARTESIA DISTRICT

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
811 S. First St., Artesia, NM 88210
District III 1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

District IV

State of New Mexico Energy Minerals and Natural Resources OCT 27 2015

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in **RECEIVED** accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

n <i>ABI</i> 5	30148	267	ICIC	asc Monn	.auoi	OPERA'		Actio	.ı ⊠ Initia	al Report	П	Final Report	
Name of Co		ion ///37	7	Contact Mike McMahan Production Assistant Foreman									
Address 64				Telephone No. 575.706.4165									
Facility Na				Facility Type Oil									
	T7 (
Surface Owner Federal Mineral Owner						r Federal A				PI No. 30-015-36376			
LOCATION OF RELEASE													
1 1 1 1 2 1									East/West Line County				
P 20 16S 28E 400						FSL	330	ŀ	FEL	EDDY			
Latitude: Longitude:													
NATURE OF RELEASE													
Type of Rele	ase Spill (Volume of Release Volume Recovered										
						1 BBL oil & 4 BBL produced 1 BBL oil & 3 BBL produced v						ed water	
Course of Dolores Course have blowned as a second						water							
Source of Release Stuffing box blow out on pump jack						Date and Hour of Occurrence 10.18.15 at 1:00 pm Date and Hour of Discovery 10.18.15 at 1:00 pm						У	
Was Immediate Notice Given?						If YES, To Whom?							
☐ Yes ☐ No ☐ Not Required													
						Jim Amos OCD							
By Whom? Mike McMahan						Date and Hour 10.19.15 at 9:45 am							
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse							
☐ Yes ⊠ No						,	•						
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Perrodial Action Taken *													
Describe Cause of Problem and Remedial Action Taken.* Stuffing box blew out on pump jack. Lease operator shut down valve.													
Stating Not men out on paint jacin nease operator shart ture.													
Describe Ar	es Affected	and Cleanur	Action 7	akan *									
				eased. A vacuur	n truck	recovered 1	BBL oil and 3	BBL pro	oduced wate	er. All this oc	curre	ed on	
location on an 8 x10 area near the wellhead and a 3x10 area near the pump jack. An environmental agency will be contacted for remediation.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
				d/or file certain									
				c of a C-141 repo									
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
rederal, state,	, or rocui ru	wa unusor regu	itations.			** * *	OIL CO	NSER	VATION	DIVISIO	N		
Signature: Jeanette Barron													
						Signed By M1/4 Exercice							
Printed Name: Jeanette Barron						Approved by Environmental Specialist:							
Title: Field Admin Support						Approval Da	ic: 10 28	15_	Expiration	Date: N/	1_		
E mail Adde	acci Icame44	a haman@d.	in com			Conditions -	f Annrovali						
E-mail Address: Jeanette.barron@dvn.com							Remediation per O.C.D. Rules & Guide ines						
Date: 10.27.15 Phone: 575.748.1813							SUBMIT REMEDIATION PROPOSAL NO						
Attach Additional Sheets If Necessary LATER THAN:												22/1	
										7.K	Y-	ココロレ	

Bratcher, Mike, EMNRD

From: Barron, Jeanette < Jeanette.Barron@dvn.com>

Sent: Tuesday, October 27, 2015 2:34 PM

To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD

Cc: Fulks, Brett; Sanchez, Gilbert; McMahan, Mike

Subject: C-141 Shakespeare 20 Fed Com 1H

Attachments: C-141 Shakespeare 20 Fed Com 1H 10.18.15.doc; Shakespear 20 Fed 1H Pic 1 of 2JPG;

Shakespear 20 Fed 1H Pic 2 of 2, JPG; Shakespear 20 Fed 1H mapping.pdf

Please see attached.

Thanks,

Jeanette Barron

 $Field\ Admin\ Support\text{-}Production$

Devon Energy Corporation

P.O. Box 250 Artesia, NM 88211 575 748 1813 Direct jeanette.barron@dvn.com

devon



checkup. ©

October is Breast Cancer Awareness Month! Don't forget to remind someone you love to get a yearly

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.