

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1530234949

6137

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production Company	Contact Joah Weidemann; Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-513-1528
Facility Name Cotton Draw Unit SWD 181	Facility Type Salt Water Disposal

Surface Owner: Federal	Mineral Owner: Federal	API No 30-015-41649
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter H	Section 36	Township 24S	Range 31E	Feet from the 1568	North/South Line North	Feet from the 1189	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: N 32.1767786

Longitude: W 103.7268063

NATURE OF RELEASE

Type of Release produced water spill	Volume of Release 100BBLS	Volume Recovered 30BBLS
Source of Release Load line valve left open	Date and Hour of Occurrence February 24, 2015 3:00 PM	Date and Hour of Discovery February 24, 2015 3:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson; BLM & Mike Bratcher; OCD	
By Whom? Assistant Production Foreman; Kevin Phillips	Date and Hour February 24, 2015 @6:45PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A


Describe Cause of Problem and Remedial Action Taken.*

A load line valve was left open resulting in 100BBLS of produced water being released onto the location. The valve was shut as soon as the release was noticed.

Describe Area Affected and Cleanup Action Taken.*

The 100BBLS of released produced water affected an area approximately 50' x 100' on the southwest side of the location. A vacuum truck recovered 30BBLS of the released fluid. The produced water did not leave the pad and did not reach the pasture.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sandy Farley	OIL CONSERVATION DIVISION	
Printed Name: Sandra Farley	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 10/29/15	Expiration Date: N/A
E-mail Address: sandy.farley@dm.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input checked="" type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	
Date: 2.26.15 Phone: 575.746.5587	LATER THAN: 11/29/15	

* Attach Additional Sheets If Necessary

NM OIL CONSERVATION
ARTESIA DISTRICT

OCT 28 2015

RECEIVED

2RP.3362

Patterson, Heather, EMNRD

From: Rebecca Pons <office2@sesi-nm.com>
Sent: Wednesday, October 28, 2015 1:40 PM
To: Patterson, Heather, EMNRD
Subject: API 30-015-41649
Attachments: c-141 INTITIAL.pdf

Hi Heather,

I have attached the C-141 for the spill associated with the Devon Cotton Draw Unit SWD 181. Could you provide me with an RP number, once you have it in your system? I am in the process of drafting the work plan for your approval.

Thank You

Rebecca Pons

Safety & Environmental Solutions, Inc.
703 East Clinton Street
Hobbs, NM 88240
Office: (575) 397-0510