

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAME <u>NAB1530829829</u>		OPERATOR	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Name of Company <u>Devon Energy Production</u>		Contact <u>Dan Suniga Production Foreman</u>	
Address <u>6488 Seven Rivers Hwy Artesia, NM 88220</u>		Telephone No. <u>575.513.1930</u>	
Facility Name <u>Ore Ida 14 Fed 10</u>		Facility Type <u>SWD</u>	
Surface Owner <u>Federal</u>		Mineral Owner <u>Federal</u>	API No. <u>30-015-29290</u>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	14	24S	29E	1780	FSL	860	FEL	EDDY

Latitude: 32.215079 **Longitude:** -103.948767

NATURE OF RELEASE

Type of Release Spill <u>Produced water</u>	Volume of Release <u>25 BBL</u>	Volume Recovered <u>0 BBL</u>
Source of Release <u>Hole in 3 inch poly pipe</u>	Date and Hour of Occurrence <u>10/27/15 at 1:30 PM</u>	Date and Hour of Discovery <u>10/27/15 at 1:30 PM</u>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>Jim Amos -BLM</u> <u>Mike Bratcher -OCD</u>	
By Whom? <u>Leonard Aguilar</u>	Date and Hour <u>10/28/15 at 12:30</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse <u>N/A</u>	
If a Watercourse was Impacted, Describe Fully.* <u>N/A</u>		
Describe Cause of Problem and Remedial Action Taken.* <u>3 inch poly pipe ran over creating a hole which resulted in release. Transfer pumps shut off to prevent further release. The poly pipe is scheduled for repair.</u>		
Describe Area Affected and Cleanup Action Taken.* <u>25 BBL spill of produced water was released on a 12 x 50 area on the lease road leading to the Ore Ida 14 Fed 10 SWD 0 BBL recovered. An environmental group will be contacted for remediation.</u>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <u>Jeanette Barron</u>	OIL CONSERVATION DIVISION	
Printed Name: <u>Jeanette Barron</u>	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: <u>Field Admin Support</u>	Approval Date: <u>11/4/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>Jeanette.barron@dmv.com</u>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	
Date: <u>11/3/15</u> Phone: <u>575.748.1813</u>	LATER THAN: <u>12/4/15</u>	

* Attach Additional Sheets If Necessary

220.3374

Patterson, Heather, EMNRD


From: Barron, Jeanette <Jeanette.Barron@devon.com>
Sent: Tuesday, November 03, 2015 3:58 PM
To: jamos@blm.gov; Shelly Tucker (stucker@blm.gov); Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Fulks, Brett; Aguilar, Leonard; Carter, Ray
Subject: C-141 Ore Ida 14 Fed 10 SWD
Attachments: C-141 Ore Ida 14 Fed 10 SWD 10.27.15.doc; Ore Ida 14 Fed 10 SWD spill.pdf; Ore Ida 14 Fed 10 SWD.jpg

Categories: printed

Please see attached

Thanks,

Jeanette Barron
Field Admin Support-Production

Devon Energy Corporation
P.O. Box 250
Artesia, NM 88211
575 748 1813 Direct
jeanette.barron@devon.com

devon

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.