-

.

÷

.

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011 .

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

1220 S. St. Fran	icis Dr., Santa	Fe, NM 87505	5	Sa	inta Fe	, NM 875	05						
			Rele	ease Notific	ation	and Co	rrective A	ction	,				
NABI	5.3083	5676				OPERAT	FOR		🛛 Initia	al Report		Final Report	
Name of Co	ompany: B	OPCO, L.P.	D131	(Contact: Amy Ruth								
			oad, N.M. 8822		Telephone No. 575-887-7329								
Facility Na	me: BEU I	Hackberry 3	#001		Facility Type: Tank Battery/SWD								
Surface Ow	ner: Feder	al	Mineral C)wner:	Federal API				No. 30-015-40288				
				LOCA	ATION	N OF REI	EASE						
Unit Letter	Section	Township	Feet from the		South Line Feet from the East/West Line County								
A ,	Jnit LetterSectionTownshipRangeFeet from theNoA3419S31E800No				North		825	East Eddy					
L,	<u> </u>		іт	iatitude32.62	1	Longitude	-103 850001	。		I			
			L					_					
Turne of Bala	D	- durand Wate		NAI	URE	OF REL			Volume I	Concuered	200 66	e	
Type of Rele Source of Re		roduced Wate							Recovered 390 bbls Hour of Discovery				
Source of Ite		ige pump con	10/25/2015 time unknown 10/25/2015										
Was Immedi	iate Notice C	Jiven?	If YES, To Whom?										
By Whom?	Dend Dlavia		I Mike Bratcher/Heather Patterson (NMOCD), Jim Amos (BLM) Date and Hour 10/25/2015 7 pm										
By Whom? Was a Water					If YES, Volume Impacting the Watercourse.								
			Yes 🛛	No		N/A							
If a Waterco	urse was Im	pacted, Descr	ribe Fully	*		<u> </u>				-NM-OIL	. CO I	VSERVATIO	
		p, =								Ақ	TESIA	DISTRICT	
Describe Co	100 6 C D 1-1	em and Reme	dial A -4'-	- Teles	<u> </u>					N	0∀ ∩	3 2015	
				ailed. The conne	ction wa	s repaired.					•	0 2015	
			,			l				Ę		IVED	
										,		IVED	
		and Cleanup										····	
				pad within the fer						is. The imp	acted a	rea was	
scraped and	132 cubic ya	ards of satura	ted caliche	e surface soils we	re remov	ca to a NMU	CD approved dis	posal la	unty.				
L hereby cer	tify that the	information n	uven abov	e is true and com	nlete to t	he best of my	knowledge and i	understa	d that pur	suant to NM	IOCD I	ules and	
regulations a	all operators	are required	to report a	nd/or file certain	release n	otifications a	nd perform correct	ctive act	ions for re	leases which	i may e	ndanger	
public health	h or the envi	ronment. The	e acceptan	ce of a C-141 rep	ort by th	e NMOCD m	arked as "Final R	(ceport d	oes not rel	lieve the ope	rator o	f liability	
should their	operations h	ave failed to	adequately	y investigate and ptance of a C-141	remediat	e contaminati	ion that pose a thr	reat to gr	ound wate	r, surface w	ater, hu	uman health	
federal, state	c, or local la	ws and/or reg	ulations.	plance of a C-141	report d	oes not renev	e the operator of	respons.	ionity for (compliance v	with an	y ouler	
	$\sqrt{7}$	XT.	TL)			OIL CON	ISERV	ATION	DIVISI	ON		
Signature:	N.												
olgitaturo.	1 Joury	\sim			Approved by Environmental Specialist:								
Printed-Nan	ne: Amy l	Auth							i/n	0/1	L		
Title: A	ssistant Rem	ediation Fore	man			Approval Da	te: 11 4 11	5	Expiration	Date: N	<u>1</u> A		
E-mail Add	ress: AC	Ruth@basspe	et.com			Conditions o	f Approval:				, —		
							ion per O.C.E). Rule	s & Gui	Attached delines	i [_]		
Date: 11/0 Attach Add		ota [f Nasa-		ne: 432-661-0571		SUBMIT F	EMEDIAŢIO	N PRO	POSAL	NO	0 0		
Anacii Add	monal She	ets II Neces	sai y				IAN: 124		·		ZKI	P-337(

Patterson, Heather, EMNRD

From: Sent: To: Subject: Attachments: Ruth, Amy C. <ACRuth@BassPet.Com> Tuesday, November 03, 2015 1:29 PM Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD BEU Hackberry 34 Federal #1 Initial C-141 Hackberry 34 Federal 1 - Initial C-141.pdf

Please find the attached initial form C-141 for the leak at the BEU Hackberry 34 Federal #1 SWD on 10/25/2015.

Thanks!! 🙂

Amy C. Ruth BOPCO, L.P. EH&S Remediation Specialist 522 W. Mermod, Suite 704 Carlsbad, NM 88220 Office: (575)887-7329 Fax: (575)887-7473 Cell: (432)661-0571

.

1