

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Linn Operating, Inc.	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name: Skelly B Battery- Skelly B #130	Facility Type: Battery

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-22264
-----------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter A	Section 28	Township 17S	Range 31E	Feet from the 760	North/South Line North	Feet from the 760	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.86647 Longitude 103.8571

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 320bbls	Volume Recovered: 195
Source of Release: 1/2" nipple on filter	Date and Hour of Occurrence 05/15/2013 7:15 A.M.	Date and Hour of Discovery: 05/15/2013 7:15 A.M.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher-Nin OCD/ Mike Burton-BLM	
By Whom?	Date and Hour 01-22-13 2:20 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*
Drove up to location at about 7:15 A.M. and found a busted 1/2" nipple leaking from the filter on the transfer pumps

Describe Area Affected and Cleanup Action Taken.*
Water ran from the pumps about 30 feet on to the lease road and turned east about 260x30 foot are on the lease road. All fluids stayed on the lease roads around the battery on the pad. The closest well to the impacted area was the Skelly B #130. A roustabout company was contacted and the leak repaired. Vacuum trucks picked up 195 bbls from the ground surface.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Fred B Wall</u>		OIL CONSERVATION DIVISION	
Printed Name: Brian Wall		Approved by Environmental Specialist <u>[Signature]</u>	
Title: Construction Foreman II		Approval Date: <u>11/6/15</u>	Expiration Date:
E-mail Address: bwall@linenergy.com		Conditions of Approval: <u>[Signature]</u>	Attached <input type="checkbox"/>
Date: Phone: 806-367-0645			

* Attach Additional Sheets If Necessary

2RP-1655