

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

JAN 06 2015
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: Hudson Federal Battery #1 On Pad with Hudson Federal well #7 (2RP-1732)	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-31513

LOCATION OF RELEASE

Unit Letter F	Section 1	Township 23S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.336050 Longitude W 103.836788

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 15 bbls	Volume Recovered: 8 bbls
Source of Release: Water transfer pump	Date and Hour of Occurrence 5/17/13 time unknown	Date and Hour of Discovery 5/17/13 9:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A 1/4" plug vibrated out of a water transfer pump causing water to spill inside of the 0 perm containment and sprayed outside on the ground. The plug was replaced.		
Describe Area Affected and Cleanup Action Taken.* Approximately 1800 sq. ft of tank battery pad and approximately 400 sq. ft. of pasture. The free standing fluid was recovered. The spill area will be remediated according to the NMOCD and BLM remediation guidelines. <i>The spill was remediated in conjunction with a pit remediation and re-cap for the Hudson Federal #1 well, and the Hudson Federal #7 pumping well. A C-144 was submitted and approved for a trench burial for some of the pit material; a separate C-105 was filed for the pit closure. Please reference the Closure Request dated December 2014.</i>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <u>Tony Savoie</u>		OIL CONSERVATION DIVISION
Printed Name: Tony Savoie		Approved by Environmental Specialist: <u>Huffman</u>
Title: Waste Management and Remediation Specialist		Approval Date: <u>11/4/15</u> Expiration Date: <u>N/A</u>
E-mail Address: <u>tasavoie@basspet.com</u>		Conditions of Approval: <u>Final</u> Attached <input type="checkbox"/>
Date: 1/6/15 Phone: 432-556-8730		

* Attach Additional Sheets If Necessary

2RP-1732