

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1531455437		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Devon Energy Production 14137		Contact Mike McMahan Assistant Foreman		
Address 6488 Seven Rivers Hwy Artesia, NM 88220		Telephone No. 575.706.4165		
Facility Name State BW Com I		Facility Type Gas		

Surface Owner State	Mineral Owner State	API No. 30-015-23996
----------------------------	----------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter H	Section 27	Township 18S	Range 28E	Feet from the 1980	North/South Line FNL	Feet from the 660	East/West Line FEL	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude: 32.720956 **Longitude:** -104.157078

NATURE OF RELEASE

Type of Release Spill Oil	Volume of Release 165 BBL	Volume Recovered 48 BBL
Source of Release Hole in tank	Date and Hour of Occurrence 11/03/15 at 4:35 pm	Date and Hour of Discovery 11/03/15 at 4:35 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos BLM Mike Bratcher OCD	
By Whom? Mike McMahan	Date and Hour 11/03/15 5:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

NM OIL CONSERVATION
ARTESIA DISTRICT

NOV 06 2015

RECEIVED

If a Watercourse was Impacted, Describe Fully.* N/A


Describe Cause of Problem and Remedial Action Taken.*

A hole in the water tank caused a leak in the dirt dike containment. This tank was already isolated so production was being routed to another tank. A vacuum truck was called out for recovery.

Describe Area Affected and Cleanup Action Taken.*

A 165 BBL oil spill accorded on a 4 X 30 area in a dirt dike containment 48 BBL was recovered. An environmental company will be called out for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Jeanette Barron	OIL CONSERVATION DIVISION	
Printed Name: Jeanette Barron	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 11/10/15	Expiration Date: N/A
E-mail Address: Jeanette.barron@dmv.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Reached <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	
Date: 11-6-15 Phone: 575.748.1813	LATER THAN: 12/12/15	

* Attach Additional Sheets If Necessary

2RP-3379

Patterson, Heather, EMNRD

From: Barron, Jeanette <Jeanette.Barron@devon.com>
Sent: Friday, November 06, 2015 10:03 AM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: McMahan, Mike; Sanchez, Gilbert; Fulks, Brett
Subject: C-141 State BW Com 1 11.03.15
Attachments: C-141 State BW Com 1.doc; State BW Com 1 Pic 2 of 3.jpg; State BW Com 1 Pic 3 of 3.jpg; State BW Com 1 spill.pdf; State BW Com 1 Pic 1 of 3.jpg

Please see attached.

Thanks,

Jeanette Barron

Field Admin Support-Production


Devon Energy Corporation

P.O. Box 250

Artesia, NM 88211

575 748 1813 Direct

jeanette.barron@devon.com


devon

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.

**ENVIRONMENTAL RELEASE NOTIFICATION
Call-In Sheet**

Date: 11/4/15
Mike McMahon ⁵⁷⁵⁻ 706-4165 from Devon
(Person Reporting) (Company)

is reporting a release at the State BW Com #1
(Site)

API# 30-015-23996, Sec. 27 T 18s - R 28s.

Occurred on: _____ at _____ AM/PM.
(Date of Occurrence) (Time of Occurrence)

Volume released: 165 bbls

C-141 received: 11/6/15

Volume recovered: _____

2RP- 3379

Briefly Describe Cause of Problem and action taken: Able in bottom of Tank
contained in vented berm

(_____) (Initials)

**FLARE NOTIFICATION
Call-In Sheet**

Date: _____

Report Flare for _____ from _____
(Reporting Company) (Person Reporting)

Occurred on: _____ at _____ AM/PM.
(Date) (Time of Occurrence)

C-129/C-141 received: _____

Flared Inlet Gas for: _____

Total MCF: _____

Briefly Describe Cause of Problem and action taken: _____

(_____) (Initials)