

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

NOV 25 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Release Notification and Corrective Action

NAB1533430359

OPERATOR

Initial Report Final Report

Name of Company <i>Devon Energy Production Company</i> <i>6137</i>		Contact <i>Dan Suniga; Production Foreman</i>
Address <i>6488 Seven Rivers Hwy Artesia, NM 88210</i>		Telephone No. <i>575-390-5850</i>
Facility Name <i>Grandi 22 - 2H</i>		Facility Type <i>Oil Well</i>
Surface Owner <i>Private</i>	Mineral Owner <i>Private</i>	API No <i>30-015-42821</i>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	22	22S	27E	1360	North	255	West	Eddy

Latitude: 32.3817083 N

Longitude: 104.1852271 W

NATURE OF RELEASE

Type of Release <i>Oil Release</i>	Volume of Release <i>6 BBLs</i>	Volume Recovered <i>6 BBLs</i>
Source of Release <i>Victaulic clamp on vapor recovery tower at fill line</i>	Date and Hour of Occurrence <i>November 20, 2015 4:00 PM</i>	Date and Hour of Discovery <i>November 20, 2015 4:00 PM</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>OCD: Mike Bratcher BLM: Jim Amos</i>	
By Whom? <i>Mike McMahan; Assistant Production Foreman</i>	Date and Hour <i>OCD: November 20, 2015 @ 5:00 PM BLM: November 20, 2015 @ 5:00 PM</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse <i>N/A</i>	
If a Watercourse was Impacted, Describe Fully.* <i>N/A</i>		
Describe Cause of Problem and Remedial Action Taken.* <i>Victaulic clamp on fill line at the vapor recovery tower failed. Production redirected from tower to tanks. Victaulic clamp has been repaired and is back in use.</i>		
Describe Area Affected and Cleanup Action Taken.* <i>6 BBLs of oil was released from fill line at Victaulic clamp. All 6 BBLs were released into lined containment. Vacuum truck recovered all of the released oil. No holes were found in the liner. No further action required.</i>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Sandy Farley</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Sandra Farley</i>	Signed By <i>Mike Bratcher</i>	
Title: Field Admin Support	Approval Date: <i>11/30/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>sandy.farley@dvn.com</i>	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date: <i>11/24/2015</i>	Phone: <i>575.746.5587</i>	

* Attach Additional Sheets If Necessary

2RP-3415

Bratcher, Mike, EMNRD

From: Farley, Sandy <Sandy.Farley@dvn.com>
Sent: Wednesday, November 25, 2015 1:46 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: Grandi 22-2H Oil Spill 6BBLS 11.20.15
Attachments: Grandi 22-2H Oil Spill 6BBLS 11.20.15 Initial & Final C-141.doc; Grandi 22-2H Oil Spill 6BBLS 11.20.15 pic 3 of 5.jpg; Grandi 22-2H Oil Spill 6BBLS 11.20.15 pic 4 of 5.jpg; Grandi 22-2H Oil Spill 6BBLS 11.20.15 pic 5 of 5.jpg; Grandi 22-2H Oil Spill 6BBLS 11.20.15 pic 1 of 5.jpg; Grandi 22-2H Oil Spill 6BBLS 11.20.15 pic 2 of 5.jpg; Grandi 22-2H Oil Spill 6BBLS 11.20.15 GIS Image.pdf

Good afternoon,

Attached you will find the Initial & Final C-141, photos and GIS Image for the 6 BBLS oil release that occurred at the Grandi 22-2H on November 20, 2015. The red dot on the GIS Image represents the approximate location of the release. Since no image of this location is available on GIS as of yet the yellow box represents the approximate location of the Grandi 22-2H.

Have a fantastic Thanksgiving

Sandra Farley
Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, New Mexico 88211
575 746 5587



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.

ENVIRONMENTAL RELEASE NOTIFICATION

Call-In Sheet

Date: 4/2

Notice received by: Randy

Devon ⁵⁷⁵⁻⁷⁰⁰⁻⁴¹⁶⁵
Name of Company/Phone #

Grandu 22H Battery
Facility Name

30-015-42821
API #

22 22S - 27E
Sec. Township Range

11/20/15
Date of Occurrence

4/20/15 5:30pm
Date/Hour of Discovery

oil
Type of Release

Over 5 bbl
Volume of Release

Volume Recovered

Briefly Describe Cause of Problem and action taken: inside lined containment

Mike
Notice given by: Name/ Company

4/24/15
Date/Hour Immediate Notice given

Date C-141 received: 11/25/15

2RP- 3415

FLARE NOTIFICATION
Call-In Sheet

Date: _____

Notice received by: _____

Name of Company/Phone #

Facility Name

Date of Occurrence

Date/Hour of Flare

Type of Release

Flared MCF Volume

Volume Recovered

Briefly Describe Cause of Problem and action taken: _____

Notice given by: Name/ Company

Date/Hour Immediate Notice given

Date C-141 received: _____

2RP- _____