

# NM OIL CONSERVATION

ARTESIA DISTRICT

DEC 31 2015

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

NAB1600435187  
FABIS26137120

### OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: Devon Energy Production Co LP (6137)	Contact: Jeff Heath, Devon Completions Asst. Foreman
Address: PO Box 250 Artesia, NM 88211	Telephone No. 575-513-2274
Facility Name: Trionyx Treated Water Facility (22F-103)	Facility Type: Water Facility
Surface Owner: State	Mineral Owner: State
API No. NA	

### LOCATION OF RELEASE

Unit Letter P	Section 2	Township 25S	Range 31E	Feet from the 723	North/South Line South	Feet from the 135	East/West Line East	County Lea	Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------	------

Latitude: 32.154003 Longitude: -103.740557

### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 56 bbls	Volume Recovered: 56 bbl
Source of Release: Frac tank overflow	Date and Hour of Occurrence 12/18/2015, 7:00 AM	Date and Hour of Discovery 12/18/2015, 7:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD- Kellie Jones	
By Whom? Jeff Heath, Devon Completions Asst. Foreman	Date and Hour: 12/18/2015, 11:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	
If a Watercourse was Impacted, Describe Fully.* NA		

#### Describe Cause of Problem and Remedial Action Taken.\*

Frac tanks at the Trionyx Treatment Facility overflowed due to human error causing a spill of 56 barrels of produced water to overflow inside the lined containment. Pumps were shut down at the batteries to stop the overflow.

#### Describe Area Affected and Cleanup Action Taken.\*

56 barrels of produced water overflowed inside the lined containment at the Trionyx Treatment Facility. Liner was checked for holes and no holes were found; therefore the spill did not touch the pad or leave the lease. A vacuum truck was used to recover the entire spill of 56 barrels of produced water.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Denise Menoud	OIL CONSERVATION DIVISION	
Printed Name: Denise Menoud	Approved by Environmental Specialist: [Signature]	
Title: Field Admin Support	Approval Date: 11/4/16	Expiration Date: N/A
E-mail Address: Denise.Menoud@dmv.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 12/22/2015	Phone: 575-746-5544	

\* Attach Additional Sheets If Necessary

2RP- 3470

**Patterson, Heather, EMNRD**

---

**From:** Keyes, Jamie, EMNRD  
**Sent:** Thursday, December 31, 2015 2:43 PM  
**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD  
**Subject:** FW: C-141 Initial and Final - Trionyx water facility  
**Attachments:** C-141 Trionyx water facility 56 BPW 12\_18\_15 Initial and Final.pdf

I believe this one is in District 2.

---

**From:** Jones, Kellie, EMNRD  
**Sent:** Thursday, December 31, 2015 1:37 PM  
**To:** Keyes, Jamie, EMNRD  
**Subject:** FW: C-141 Initial and Final - Trionyx water facility

---

**From:** Menoud, Denise [<mailto:Denise.Menoud@dvn.com>]  
**Sent:** Tuesday, December 22, 2015 2:45 PM  
**To:** Jones, Kellie, EMNRD  
**Cc:** Heath, Jeff; Menoud, Denise; Fulks, Brett  
**Subject:** C-141 Initial and Final - Trionyx water facility

Please see attached Initial and Final C-141. Thank you.

***Denise Menoud***

Admin Field Support 4 / Completions  
Devon Energy Production Co. LP/Artesia NM  
[Denise.Menoud@dvn.com](mailto:Denise.Menoud@dvn.com)  
575-746-5544

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.