

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

FEB 17 2010

HOBBSOCD

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Apache Corporation	Contact	Natalie Gladden
Address	P.O. Box 1849 Eunice, NM 88231	Telephone No.	575-390-4186
Facility Name	EBDU Battery #5 (nearest EBDU#63)	Facility Type	Production Facility

Surface Owner	Lucille Bryant	Mineral Owner	Apache Corporation	Lease No.	30-025-38234
---------------	----------------	---------------	--------------------	-----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	14	21S	37E	1485'	South Line	2310'	East Line	Lea

Latitude\_N32 deg 28.954' Longitude\_W103 deg 07.874'\_

NATURE OF RELEASE

Type of Release	Oil/Wtr	Volume of Release	5bbls	Volume Recovered	1bbl
Source of Release	2" hammer union	Date	6/5/08	Date	5/05/08
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Larry Johnson		
By Whom?	Natalie Gladden	Date and Hour	06/05/08 11:35am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

2" hammer union caused fluid to be released. Vacuum truck recovered 1bbl of total fluid.

Describe Area Affected and Cleanup Action Taken.\*

Contaminates were extracted from inside the firewalls and hauled to Sundance Disposal. Risk Base Closure was obtained with Larry Johnson, to do a full remediation of this facility when the facility is abandoned, so that the integrity of the production vessels were not compromised during remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	Approved by District Supervisor:	
Title: EH&S Environmental Tech	Approval Date:	Expiration Date:
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 07/15/08 Phone: 575-390-4186		

\* Attach Additional Sheets If Necessary



District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Apache Corp	Contact Natalie Gladden	
Address P.O. Box 1849	Telephone No. 575-390-4186	
Facility Name EBDU Battery #5(nearest well EBDU #63)	Facility Type Battery	
Surface Owner Lucille Bryant	Mineral Owner Apache Corp	Lease No. 30-025-38234

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	14	21S	37E	1485	South Line	2310	East Line	Lea

Latitude N32 deg 28.954' Longitude W103 deg 07.874'

#### NATURE OF RELEASE

Type of Release Oil/Wtr	Volume of Release 5bbls	Volume Recovered 1bbl
Source of Release 2" hammer union	Occurred 5/5/08	Discovery 5/5/08 11:30
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson at 11:35 am	
By Whom? Natalie Gladden	Date and Hour: 05/05/08 11:35am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

RECEIVED  
MAY 12 2008  
HOBBS OCD

Describe Cause of Problem and Remedial Action Taken.\*

2" hammer union caused leak. Vacuum truck recovered 1bbl of fluid.

Describe Area Affected and Cleanup Action Taken.\*

Release was contained inside berms and Hydro-tech came to location and picked up all contaminants and hauled to Sundance. Samples will be taken inside berm area. And pea-gravel will be installed in berm area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	OIL CONSERVATION DIVISION <i>L. Johnson</i>	
Printed Name: Natalie Gladden	Approved by District Supervisor ENVIRONMENTAL ENGINEER	
Title: EH&S Environmental Tech	Approval Date: 5.14.08	Expiration Date: 7.14.08
E-mail Address: Natalie.gladden@apachecorp.com	Conditions of Approval: Submit Final C-141 w/dec by	
Date: 5-12-08 Phone: 505-390-4186	Attached <input type="checkbox"/> <i>1 RP # 1050</i>	

\* Attach Additional Sheets If Necessary

F 0040813538216

1860