




AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pPLM1004341688

1RP - 2419

CIMAREX ENERGY CO.

RP. 2419

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company <u>Smith + Marcus</u>	Contact <u>Mike Dennis</u>
Address <u>Box 863 Roswell TX</u>	Telephone No. <u>432-940-1890</u>
Facility Name <u>Knight #14</u>	Facility Type <u>Producing well</u>
Surface Owner <u>Doan</u>	Mineral Owner
Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<u>P</u>	<u>22</u>	<u>24</u>	<u>37</u>					<u>hew</u>

Latitude 32 11 57 Longitude 103 09 40

NATURE OF RELEASE

Type of Release <u>Oil + water</u>	Volume of Release <u>374 bbls</u>	Volume Recovered <u>0</u>
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? <u>2/5/10</u> <u>Geoffrey LeKing</u>	
By Whom? <u>D. Meredith</u>	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Repaired flow line | stabilized area, began hauling contamination

Describe Area Affected and Cleanup Action Taken.*

area 100x150 south of well.
Excavated contaminated soil, hauled to Doan Lt. Sampled area OCT
approved backfilling. Area was backfilled + leveled.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Mike Dennis
Printed Name: Mike Dennis
Title: Production Sept.
E-mail Address:
Date: 3/1/2010 Phone: 432-940-1890

ENV. ENGINEER:
Approved by District Supervisor: Geoffrey LeKing
Approval Date: 03/18/10 Expiration Date: -

Conditions of Approval:

Attached ☐

IRP-10.2.2419

* Attach Additional Sheets If Necessary