



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pKJ1603954488

1RP - 4173

APACHE CORP

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

HOBBS OCD
APR 30 2012

Release Notification and Corrective Action

RECEIVED

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Apache Corporation	Contact Natalie Gladden	
Address PO Box 1849 Eunice, NM 88231	Telephone No. 575-390-4186	
Facility Name DC Hardy Battery (nearest well #4)	Facility Type Production Facility	
Surface Owner Sims	Mineral Owner NMOCD	API No. 30-025-06691

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	20	21S	37E	510'	FSL	1980'	FEL	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil	Volume of Release 10	Volume Recovered 8
Source of Release Lighting/Electrical	Date and Hour of Occurrence 04/10/12	Date and Hour of Discovery 04/10/12
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Due to thunder and lightning storms the electricity was knocked out which shut down the automation communication system, which did not signal the transfer pump to kick on, causing the tank to overflow.

Describe Area Affected and Cleanup Action Taken.*

Site will be hand dug and NMOCD guidelines will be followed to closer.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.


Signature: 	Oil Conservation Division
Printed Name: Natalie Gladden	Approved by: 
Title: EHS Environmental Tech	Approval Date: 4/10/12
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval:
Date: 4/18/12 Phone: 575-390-4186	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

12P-4173

LODK P812
C-141

MBD my
APPUL



Legend


- ▲ SAMPLE POINTS
- ELECTRICAL CONTROL
- BERM
- x - x - FENCE LINE
- STAIN (287 sq ft)
- TANKS

Landowner = Apache



**APACHE DC
HARDY TANK
BATTERY NO. 1 AD**
LEGALS: UL O & P sec. 20
T-21-S R-37-E
LEA COUNTY, NM

DGW = 76 ft



GPS date: 4/10/12 DH
Drawing date: 4/16/12
Drafted by: L. Weinheimer