

AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pKJ1603954844

1RP - 4174

APACHE CORP

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210

State of New Mexico
Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

District III
1000 Rio Brazos Road, Aztec, NM 87410 APR (1) 9 2012

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 Oil Conservation Division 1220 South St. Francis Dr.

1220 S. St. 11th	vis Dr., Suite	u10,111110750.		Sa	inta F	e, NM 8/5	005						
1 1/4		Ł.	Rel	ase Notific	atio	n and Co	orrective A	ction	1				
						OPERA'	ГOR			al Report		Final Repor	
Name of Company Apache Corporation							Contact Natalie Gladden						
							Telephone No. 575-390-4186						
Facility Nar	ne NEDU	Sat #5 (nea	rest well	#920)		Facility Typ	e Production I	Facility					
Surface Owner Stephens Mineral Owner S						State API No. 30-025-21351							
				LOCA	TIO	N OF RE	LEASE						
					/South Line	Feet from the				County			
J	23	21S	37E	2310'	FSL		1980'	FEL		Lea			
3	23	210		titude		Longitud		TEE		Dea			
			La										
Tyma of Dala	aga Oil		-	NAT	URE	Volume of			Volume I	Danayarad 2	5		
Type of Release Oil Source of Release Automation failure						Volume of Release 40 Date and Hour of Occurrence			Volume Recovered 35 Date and Hour of Discovery				
						3/31/12			3/31/12				
Was Immedia	ate Notice (Yes 🗵	No Not Re	equired	If YES, To	Whom?						
By Whom?						Date and H	lour						
Was a Watercourse Reached? ☐ Yes ☐ No						If YES, Volume Impacting the Watercourse.							
IC W.	, , , , , , , , , , , , , , , , , , ,	pacted, Descr											
		em and Reme rt the transfer		n Taken.* Ising tanks to over	rflow.	Recovered sta			= 46 ¹	the contain	ment v	valls.	
Describe Are	a Affected	and Cleanup A	Action Tal	cen.*									
Once the one	-call is mad	e the affected	area will	be excavated to m	eet the	NMOCD Rul	es and Regulation	ns.					
regulations al public health should their of or the environ	or the environment. In a	are required to ronment. The lave failed to a	o report ar acceptance adequately OCD accep	is true and comp nd/or file certain re the of a C-141 report investigate and restance of a C-141	elease in the second of the se	notifications and the NMOCD matter contamination	nd perform correct arked as "Final R	tive acti eport" d	ons for rele oes not reli	eases which eve the oper	may en	ndanger f liability	
Signature:		Laure	G	ladde	ب	Approved	AP	P	R(V	E	D	
Printed Name: Natalie Gladden													
Title: EHS Environmental Tech							Approval Date: 2016 Expiration Date:						
E-mail Address: natalie.gladden@apachecorp.com						Conditions of Approval:				Attached □			


* Attach Additional Sheets If Necessary

Phone: 575-390-4186

Date: 4/2/12

IRP 4174


Initial Lab Data





APACHE NEDU SATELLITE #005 AD

UL/J SECTION 23 T-21-S R-37-E LEA COUNTY, NM



GPS date: 4/2/12 Drawing date: 4/4/12 Drafted by: L. Weinheimer