



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pKJ1604046477

1RP - 3069

APACHE CORP

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

SEP 07 2010

HOBBSOCD

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Apache Corporation	Contact	Natalie Gladden
Address	P.O. Box 1849 Eunice, NM 88231	Telephone No.	575-390-4186
Facility Name	State CK #3	Facility Type	Production well

Surface Owner	Bill Stephens	Mineral Owner	State of NM	Lease No.	30-025-20540
---------------	---------------	---------------	-------------	-----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	19	21S	37E	330'	FSL	1549'	FEL	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Hydrocarbon/Produced Water	Volume of Release	10	Volume Recovered	5
Source of Release	Nipple on tubing	Date and Hour of Occurrence	08/07/2010 10am	Date and Hour of Discovery	Same
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Natalie Gladden	Date and Hour 08/03/2010			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			



If a Watercourse was Impacted, Describe Fully.*

WATER @ 110'

Describe Cause of Problem and Remedial Action Taken.*
Nipple on tubing failed

Describe Area Affected and Cleanup Action Taken.*
Fluid was released on location pad, no fluid in the pasture area. The contamination was excavated and hauled to Sundance Disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION  Approved by District Supervisor Environmental Specialist	
Printed Name: Natalie Gladden	Approval Date: 09/07/10	Expiration Date: 11/08/10
Title: EHS Environmental Tech	Conditions of Approval: SUBMIT FINAL	
E-mail Address: natalie.gladden@apachecorp.com	C-141 BY 11/08/10	Attached <input type="checkbox"/>
Date: 08/15/2010 Phone: 575-390-4186	IRP-06-14-3069	

* Attach Additional Sheets If Necessary