



# AE Order Number Banner

## Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



**App Number:** pJXK1606054450

**1RP - 2951**

**APACHE CORP**

3/1/2016

MAR 01 2016

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

SEP 09 2013

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Apache Corporation	Contact Bruce Baker
Address PO Box 1849, Eunice, NM 88231	Telephone No. (432) 631-6982
Facility Name EBDU # 9	Facility Type Production Well

Surface Owner Paige McNeil	Mineral Owner	API No. 30-025-34937
----------------------------	---------------	----------------------

#### LOCATION OF RELEASE

Unit Letter O	Section 1	Township 21S	Range 37E	Feet from the 990'	North/South Line FSL	Feet from the 2480	East/West Line FWL	County Lea
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	---------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

#### NATURE OF RELEASE

Type of Release Oil and produced water	Volume of Release Unknown	Volume Recovered 0 bbls
Source of Release Flow line	Date and Hour of Occurrence 9/9/2013 7:00 a.m.	Date and Hour of Discovery 9/9/2013 7:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mr. Leking	
By Whom? Bruce Baker	Date and Hour 9/9/13 2:17 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The flow line plugged off with paraffin after hot watering the back side and the flow line pressured up and blew out. The site was mapped and initial samples were collected.

Describe Area Affected and Cleanup Action Taken.\*

961 square feet of pasture area was affected. A one call was placed and site will be delineated.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>	OIL CONSERVATION DIVISION <i>Larry Baker</i> Approved by Environmental Specialist	
Printed Name: Bruce Baker	Approval Date: 9/11/13	Expiration Date: 11/11/13
Title: Environmental Technician	Conditions of Approval: SUBMIT FINAL	
E-mail Address: larry.baker@apachecorp.com	C-141 BY 11/11/13	Attached <input type="checkbox"/> LRP-9-13-2951
Date: 9/11/13	Phone: (432) 631-6982	


\* Attach Additional Sheets If Necessary



# Vertical Sampling Data

## Vertical @ Pt. 1

	CI-	PID	GRO	DRO
SS	2280	4922	3960	17400
1'	1921	196.3		
2'	1587	217		
3'	2264	36		
4'	1618	246		
5'	64	0.63	<10	14.6
6'	48	0.51	<10	<10



approved for excavation & backfill  
*Jeffrey Sekins*  
 Environmental Specialist  
 NMOC-DIST 1  
 9/18/13

### Legend

- VERTICAL
- ▲ SAMPLE POINT
- SURFACE POLY LINE
- STAIN (951 sq ft)

CI- FIELD DATA

CI- LAB DATA

DGW = 77 ft

Landowner: WFM Ranch Ltd

Source: Esri, DigitalGlobe, GeoEye, i-cubed, USDA, USGS, AEX, Getmapping, Aerogrid, IGN, IGP, swisstopo, and the GIS User Community



**APACHE**  
**EBDU #009**  
**1RP-9-13-2951**  
 LEGALS: UL/V sec. 1  
 T-21-S R-37-E  
 LEA COUNTY, NM

SEP 17 2013



RECEIVED

0 10 20  
 Feet

GPS date: 9/13/13 EC  
 Drawing date: 9/17/13  
 Drafted by: L. Weinheimer