



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pJXK1606054450

1RP - 2951

APACHE CORP

2/29/2016

MAR 01 2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

SEP 09 2013

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Apache Corporation	Contact	Bruce Baker
Address	PO Box 1849, Eunice, NM 88231	Telephone No.	(432) 631-6982
Facility Name	EBDU # 9	Facility Type	Production Well

Surface Owner	Paige McNeil	Mineral Owner		API No.	30-025-34937
---------------	--------------	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	I	21S	37E	990'	FSL	2480	FWL	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	Unknown	Volume Recovered	0 bbls
Source of Release	Flow line	Date and Hour of Occurrence	9/9/2013 7:00 a.m.	Date and Hour of Discovery	9/9/2013 7:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mr. Leking		
By Whom?	Bruce Baker	Date and Hour	9/9/13 2:17 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The flow line plugged off with paraffin after hot watering the back side and the flow line pressured up and blew out. The site was mapped and initial samples were collected.

Describe Area Affected and Cleanup Action Taken.*

961 square feet of pasture area was affected. A one call was placed and site will be delineated.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>	OIL CONSERVATION DIVISION <i>Larry Baker</i> Approved by Environmental Specialist	
Printed Name: Bruce Baker	Approval Date: 9/11/13	Expiration Date: 11/11/13
Title: Environmental Technician	Conditions of Approval: SUBMIT FINAL	
E-mail Address: larry.baker@apachecorp.com	C-141 BY 11/11/13	Attached <input type="checkbox"/>
Date: 9/11/13 Phone: (432) 631-6982		IRP-9-13-2951

* Attach Additional Sheets If Necessary